

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CONT

REPORT SOURCE L 6 0 5 0 0 0 3 2 1 7 0 2 1 8 8 2 8 0 3 0 4 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While the plant was in steady state operation at 2386 MWt, 1P33-N001B,  
0 3 | Drywell H<sub>2</sub> - O<sub>2</sub> Analyzer, was found to be out of expected values while  
0 4 | performing normal surveillance. Tech Specs Section 3.2-11 requires one  
0 5 | system to be operable. Redundant analyzer 1P33-N001A was operable. Plant  
0 6 | operation was not affected as a result of this event. There was no effect  
0 7 | upon public health or safety due to this event. This is a repetitive  
0 8 | event as last reported on Reportable Occurrence Report No. 50-321/1981-080.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the event has been attributed to calibration drift.

1 1 | The instrument was recalibrated and returned to service.

1 2 |

1 3 |

1 4 |

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION			
1	5	E	0	9	8	NA			B	Performing Normal Surveillance					
ACTIVITY CONTENT RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE									
1	6	Z	Z	NA		NA									
PERSONNEL EXPOSURES			TYPE DESCRIPTION			NA									
1	7	0	0	0	Z										
PERSONNEL INJURIES			NUMBER DESCRIPTION			NA									
1	8	0	0	0											
LOSS OF OR DAMAGE TO FACILITY			TYPE DESCRIPTION			NA									
1	9	Z													
PUBLICITY ISSUED			DESCRIPTION			8204280258			NRC USE ONLY						
2	0	N													

NAME OF PREPARER R. T. Nix, Supt. of Maint.

PHONE: 912-367-7851

LER No.: 50-321/1982-017  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket No.: 50-321

Narrative Report  
for LER 50-321/1982-017.

While the plant was in steady state operation at 2386 MWt, 1P33-N001B, Drywell H<sub>2</sub> - O<sub>2</sub> Analyzer, was found to be out of expected values 0%  $\pm$  .1% O<sub>2</sub>. As found data at 0% input was .3% while performing normal surveillance, HNP-1-3882, H<sub>2</sub> - O<sub>2</sub> Analyzers. Tech Specs Section 3.2-11 requires one system to be operable. Redundant analyzer 1P33-N001A was operable. Plant operation was not affected as a result of this event. There was no effect upon public health or safety due to this event. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-321/1981-80.

The cause of the event has been attributed to calibration drift. The instrument was recalibrated and returned to service.

The surveillance of HNP-1-3882 is performed weekly instead of monthly as required by Tech Specs.

A generic review reveals no inherent problems.