

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C A D I C P 1 02 0 0 1 0 - 1 0 0 0 0 - 0 0 03 4 1 1 1 1 04 05

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 56

CON'T 01 REPORT SOURCE 02 0 5 0 0 0 2 7 5 07 0 2 1 2 8 2 08 0 4 2 2 8 2 09

DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Prior to fuel load, the operators received a vital instrument AC panel

03 undervoltage alarm in the control room. An operator was dispatched to

04 investigate the source of the undervoltage alarm. When the feeder breaker

05 to inverter IY-11 was manually switched off to check for a tripped breaker,

06 inverter IY-11 tripped. The operator immediately placed panel PY-11 on

07 back-up power and proceeded to check the remainder of the breakers and

08 discovered the feeder breaker to panel PY-15 in the (continued on attachment)

09

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15

01 E B 02 X 03 Z 04 C K I T B R K 05 A 06 Z

17 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31

01 8 2 02 0 9 3 03 0 3 04 X 05 1

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 38 NPD-4 FORM SUB. 39 PRIME COMP. SUPPLIER 40

01 X F 02 Z 03 Z 04 0 0 0 0 05 Y 06 N 07 L 08 W 1 2 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The causes of the undervoltage alarm and the panel PY-15 trip are unknown.

11 Investigations into possible causes revealed no problems and equipment has

12 since operated as designed. Inverter IY-11 tripped when normal AC power was

13 removed because of blown fuses in the DC power supply. The cause of the

14 blown fuses is unknown. Sample pumps to the Plant (continued on attachment)

15

FACILITY STATUS 7 8 9 % POWER 10 OTHER STATUS 11 METHOD OF DISCOVERY 12 DISCOVERY DESCRIPTION 13

01 B 02 0 0 0 0 03 NA 04 A 05 Plant Annunciator

ACTIVITY CONTENT 14 15 RELEASED OF RELEASE 16 AMOUNT OF ACTIVITY 17 LOCATION OF RELEASE 18

01 Z 02 Z 03 NA 04 NA 05

PERSONNEL EXPOSURES 19 NUMBER 20 TYPE 21 DESCRIPTION 22

01 0 0 0 0 02 Z 03 NA

PERSONNEL INJURIES 23 NUMBER 24 DESCRIPTION 25

01 0 0 0 0 02 NA

LOSS OF OR DAMAGE TO FACILITY 26 TYPE 27 DESCRIPTION 28

01 Z 02 NA

PUBLICITY 29 ISSUED 30 DESCRIPTION 31

01 N J 02 NA

NRC USE ONLY 32 33 34 35 36 37 38 39 40

NAME OF PREPARER W. B. ScottPHONE: (805) 595-7351

8204280288

ATTACHMENT TO LER 82-003/03X-1

Item 10, Event Description and Probable Consequences - continued

tripped condition. PY-15 was placed on back-up power. The breaker was reset and PY-15 was placed back on normal power. From 1137 hours, when inverter IY-11 tripped until 1600 hours, both channels of the Plant Vent Radiation Monitor (RM 14A & B) were inoperable because the sample pumps do not restart when power to the monitor is restored. Furthermore, from 1120 hours, when it is suspected that PY-15 tripped, until 1210 hours, when power to the panel was restored, the Plant Vent Iodine Monitor (RM-24) and the Plant Vent Flow Recorder (FR-12) were inoperable. Technical Specification 3.3.3.10 requires at least one channel of each monitor and flow recorder be operable at all times. The appropriate Technical Specification Action Statements were entered and satisfied. Since the plant has not attained criticality, no release of radioactive effluents occurred. This event in no way affects public health and safety. Reportable per Technical Specification 6.9.1.13.b.

Item 27, Cause Description and Corrective Actions - continued

Vent Radiation Monitors were not immediately restarted because loss of the sample pumps does not cause a channel failure alarm. A design change has been recommended to provide sample pump alarms in the control room.