

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:				(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
S C N E E 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5		LICENSEE CODE		LICENSE NUMBER	
CON'T		REPORT SOURCE		DOCKET NUMBER	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES		EVENT DATE		REPORT DATE	
Non-destructive testing of the HPI nozzle areas revealed that the 2A2 thermal sleeve was loose and that there were cracks in the ID of the safe end and piping.					
The 2B1 thermal sleeve was loose. The 2B2 thermal sleeve had a 360 degree crack in the rolled area. A rupture in this line would be classified as a small break LOCA, an accident for which FSAR analysis shows that the plant could be safely shut down. Thus, the health and safety of the public were not affected.					
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE					
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.					
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER					
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS					
The apparent cause of the cracking in the 2A2 safe end and piping appears to be thermal fatigue resulting from a loose thermal sleeve. The 2A2 cracked piping, safe end, and thermal sleeve were replaced. The 2B2 thermal sleeve was replaced. The 2B1 thermal sleeve was hard roll expanded to return the thermal sleeve to its intended condition.					
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION					
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE					
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION					
PERSONNEL INJURIES NUMBER DESCRIPTION					
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION					
PUBLICATION ISSUED DESCRIPTION					
NAME OF PREPARER J. F. Norris					

NAME OF PREPARER J. F. Norris

PHONE: (704) 373-2844