

ALJMF200-00000-0003411111  
L05000364022882032582  
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 0400 on 2/28/82 the instrumentation loop associated with FT-474 (S.G. "A" flow transmitter) was declared inoperable when its reading was out of tolerance with the other channels. Tech. Spec. section 3.3.2, in part, requires this instrumentation loop to be operable. Tech. Spec. 3.3.2 action statement requirements were met. The health/safety of the public was not affected.

SYSTEM CODE: I B 11  
CAUSE CODE: E 12  
CAUSE SUBCODE: B 13  
COMPONENT CODE: V A L V E X 14  
COMP SUBCODE: D 15  
VALVE SUBCODE: X 16  
EVENT YEAR: 8 2  
SEQUENTIAL REPORT NO.: 0 0 9  
OCCURRENCE CODE: 0 3  
REPORT TYPE: L  
REVISION NO.: 0  
ACTION TAKEN: A 18  
FAILURE ACTION: Z 19  
EFFECT ON PLANT: Z 20  
SHUTDOWN METHOD: Z 21  
HOURS: 0 0 0 0  
ATTACHMENT SUBMITTED: N 23  
NFRD-4 FORM SUB: N 24  
PRIME COMP. SL. PREFERRED: A 25  
COMPOUND MANUFA: K 0 8 5

The cause of this event was a leaking equalizing valve. The valve stem was repaired and upon satisfactory completion of FNP-2-STP-213.19A (Steam Generator 2A FT-474 Loop Calibration and Functional Test) the instrumentation loop associated with FT-474 was declared operable at 1540 on 2/28/82.

FACILITY STATUS: C 28  
% POWER: 0 2 6 29  
OTHER STATUS: NA 30  
METHOD OF DISCOVERY: B 31  
DISCOVERY DESCRIPTION: Routine Inspection 32  
ACTIVITY CONTENT RELEASED OF RELEASE: Z 33  
AMOUNT OF ACTIVITY: NA 35  
LOCATION OF RELEASE: NA 36  
PERSONNEL EXPOSURES NUMBER: 0 0 0 37  
TYPE: Z 38  
DESCRIPTION: NA 39  
PERSONNEL INJURED NUMBER: 0 0 0 40  
DESCRIPTION: NA 41  
LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42  
DESCRIPTION: NA 43  
PUBLICITY: N 44  
DESCRIPTION: NA 45