

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8		8
3	8		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 H 0 0 0 NA B Maintenance Personnel Observation

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION (39)						
1	7	0	0	0	(37)	Z	(38)	NA		

		LOSS OF OR DAMAGE TO FACILITY		
		TYPE	DESCRIPTION	(43)
7	8	9	10	
1	9	Z	(42) NA	

PHONE: 912-367-7851

LER No.: 50-366/1982-026
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1982-026.

With the reactor in refueling, personnel found the temporary changes made to procedure HNP-2-3191, Channel Logic Time Response Testing, were not reviewed by the Plant Review Board within the required 14 days (Tech Specs 6.8.3). The work for which the change was made extended beyond the 14 days and personnel were trying to complete all data prior to submitting the procedure and associated data packages. The 14 day limit was exceeded due to oversight. The personnel responsible for the oversight were reminded of the importance of meeting all Tech Specs requirements. The procedure review was expedited upon discovery of the event.

There was no effect on plant operation. The health and safety of the public was not affected. This event is repetitive as last reported on Reportable Occurrence Report No. 50-321/1981-057.