

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A R A N O 2 0 0 - 0 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 8 7 0 4 0 1 8 2 0 4 2 2 8 2 9
7 8 9 DOCKET NUMBER 40 41 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 On 4/1/82 while in Mode 1 operation at 100% full power, Control Element
0 3 Assembly Calculator (CEAC) No. 2 failed during performance of an excore
0 4 instrument test on Channel 'D'. Core Protection Calculator (CPC)
0 5 channels were placed in CEAC No. 2 inop. Logging of CEA positions every
0 6 4 hours was initiated as required by T.S.3.3.1.1. This occurrence is
0 7 reportable per T.S.6.9.1.9.b. CEAC No. 1 remained operable.
0 8
7 8 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE EVENT SOURCE VALVE SUBCODE
I E 11 E 12 G 13 I N S T R U 14 Y 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER NO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO 0 0 9 23 24 OCCURRENCE CODE 0 3 25 26 REPORT TYPE L 27 28 REVISION NO 0 29 30
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
Z 18 Z 19 Z 20 Z 21 0 0 0 22 N 23 N 24 N 25 C 4 9 0 26
31 32 33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 The momentary erroneous CEA position indication was apparently caused
1 1 by a computer scan inconsistency. CEAC No. 2 displayed control rods as
1 2 being farther inserted than actual as verified by other indications.
1 3 Appropriate penalties were applied by the CPC's. Position indication
1 4 had returned to normal within a short time. Performance of computer
(cont'd on attachment)
7 8 9

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 NA OTHER STATUS 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 RELEASED OF RELEASE Z 33 Z 34 NA AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Patrick Rogers

PHONE 501/964-3100

8205040643 820422
PDR ADDOCK 05000368
S PDR

LER NO. 50-368/82-009/03L-0 (cont'd)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (cont'd)

diagnostics failed to reveal any abnormality. The monthly surveillance was performed, and CEAC No. 2 was proved operable. CEAC No. 2 was returned to operable status on all CPC channels.