

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT 01 REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 4 0 3 8 2 8 0 5 0 3 8 2 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation, while conducting monthly surveillance DIS 1500-9, the LPCI
03 differential pressure switch 2-261-34B was inoperable. The safety significance was mini-
04 mal since the remaining three redundant switches were operable. There was no effect on
05 the health and safety of the public. Previous occurrence: Docket 50-237/82-13.
06
07
08

09 SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
17 8 2 0 1 1 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 G 25 G 0 8 0 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause was believed to be wear of a contact point in the mechanical linkage which
11 operates the switch. Switch movement is less than 1/64 inch between open and closed.
12 After minor adjustment of internal "zero" screw, the switch operated. The pressure
13 switch was then adjusted and repeatability was verified. DIS 1500-9 will continue to
14 be performed. No further action deemed necessary.

15 FACILITY STATUS E 28 % POWER 0 9 4 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine Surveillance 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
16 Z 33 Z 34 N/A N/A 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
17 0 0 0 37 Z 38 N/A 39
PERSONNEL INJURIES NUMBER DESCRIPTION
18 0 0 0 40 N/A 41
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
19 Z 42 N/A 43
PUBLICITY ISSUED DESCRIPTION
20 N 44 N/A 45

8205110090 820503
PDR AD0CK 05000237
PDR

NRC USE ONLY

NAME OF PREPARER

Sam Bader

PHONE:

815-942-2920, X-529



Commonwealth Edison

DEVIATION REPORT

DVR NO. 12 - 2 - 82 - 19
STA UNIT YEAR NO.PART 1 TITLE OF DEVIATION
LPCI Loop Break Detection Switch Failure
OCCURRED 4/3/82 1100
DATE TIMESYSTEM AFFECTED 1500
LPCI
PLANT STATUS AT TIME OF EVENT
MODE Run PWR(MWT) 2370 LOAD(MWE) 770
TESTING YES ☒ NO ☐DESCRIPTION OF EVENT
During DIS 1500-6, found dPIS 2-261-34B failed to operate over entire range of differential pressure input. Adjusted "zero" screw and dPIS 2-261-34B operated. Adjusted switch to trip at 26.5" of water (dp) increasing. Repeatability found to be O.K.EQUIPMENT FAILURE
☐ YES ☒ NO WORK REQUEST NO. RESPONSIBLE SUPERVISOR Alan R. Zapotocky DATE 4/3/82
10 CFR50.72 NRC RED PHONE ☐ ☒
NOTIFICATION MADE YES NOPART 2 OPERATING ENGINEER'S COMMENTS
The other three switches, 2-261-34 A, C, & D, were in calibration and operated properly. 2-261-34B was immediately readjusted and then operated properly.

<input type="checkbox"/> EVENT OF PUBLIC INTEREST	<input type="checkbox"/> 24-HOUR NRC NOTIFICATION REQ'D
<input type="checkbox"/> TECH. SPEC. VIOLATION	TELEPH N/A REGION III DATE TIME
<input type="checkbox"/> NON REPORTABLE OCCURRENCE	TELEGM/TELECOPY N/A REGION III DATE TIME
<input type="checkbox"/> 14 DAY REPORTABLE/T.S.	
<input checked="" type="checkbox"/> 30 DAY REPORTABLE/T.S. 6.6.B.2.a	
<input type="checkbox"/> ANNUAL/SPECL REPORT REQ'D	<input type="checkbox"/> CECO CORPORATE NOTIFICATION MADE IF ABOVE NOTIFICATION IS PER 10CFR21
A.I.R. #	<input type="checkbox"/> 5-DAY WRITTEN REPORT REQ'D PER 10CFR21
L.E.R. # 82-11/03L-0	F. A. Palmer 4/5/82 1534
	TELEPH CECO CORPORATE OFFICER DATE TIME

PRELIMINARY REPORT
COMPLETED AND REVIEWED John M. Almer 4-5-82
OPERATING ENGINEER DATE
INVESTIGATED REPORT & RESOLUTION
ACCEPTED BY STATION REVIEW
5/3/82 5/3/82
RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION
5/3/82
STATION SUPERINTENDENT DATE
88-5176 (FORM 15-52-1) 10-81