

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 3 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 CAT 58  
 LICENSEE CODE      LICENSE NUMBER      LICENSE TYPE

CONT  
01 L 6 0 5 0 0 0 2 4 9 7 0 4 0 7 9 2 8 0 4 2 8 8 2 9  
7 8 60 61 68 69 74 75 80  
 REPORT SOURCE      DOCKET NUMBER      EVENT DATE      REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During refueling, a routine inspection by the shift foreman revealed a cracked weld on  
03 the test tap of the condensate booster recirculation line (T.S. 6.6.B.2.d). This was of  
04 minimal safety significance since all leakage was contained in the turbine building floor  
05 sumps. There was no effect on public health or safety. Last similar occurrence on Unit  
06 3 was reported by R.O. 82-14/01T on Docket 50-249.  
07  
08

09 H H 11 E 12 B 13 P I P E X X 14 A 15 Z 16  
9 10 11 12 13 18 19 20  
 SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP. SUBCODE      VALVE SUBCODE  
17 8 2 0 1 7 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
 LER/RO REPORT NUMBER      EVENT YEAR      SEQUENTIAL REPORT NO.      OCCURRENCE CODE      REPORT TYPE      REVISION NO.  
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 G 0 8 0 26  
33 34 35 36 37 38 40 41 42 43 44 45 46 47  
 ACTION TAKEN      FUTURE ACTION      EFFECT ON PLANT      SHUTDOWN METHOD      HOURS      ATTACHMENT SUBMITTED      NPRO-4 FORM SUB.      PRIME COMP. SUPPLIER      COMPONENT MANUFACTURER

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of the leakage was a failed weld on the one inch test tap connection on the  
11 condensate booster recirculation line. The test tap was cut and capped since the tap is  
12 no longer used. No future corrective action deemed necessary.  
13  
14

15 H 28 0 0 0 29 N/A 30 A 31 Observation by Shift Foreman 32  
7 8 9 10 12 17 44 45 46 80  
 FACILITY STATUS      % POWER      OTHER STATUS      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION  
16 Z 33 Z 34 N/A 35 N/A 36  
7 8 9 10 11 44 46 80  
 ACTIVITY RELEASED      CONTENT OF RELEASE      AMOUNT OF ACTIVITY      LOCATION OF RELEASE  
17 0 0 0 37 2 38 N/A 39  
7 8 9 11 12 13 44 46 80  
 PERSONNEL EXPOSURES NUMBER      TYPE      DESCRIPTION  
18 0 0 0 40 N/A 41  
7 8 9 11 12 44 46 80  
 PERSONNEL INJURIES NUMBER      DESCRIPTION  
19 Z 42 N/A 43  
7 8 9 10 12 44 46 80  
 LOSS OF OR DAMAGE TO FACILITY TYPE      DESCRIPTION  
20 N 44 N/A 45  
7 8 9 10 12 44 46 80  
 PUBLICITY ISSUED      DESCRIPTION

8205110107 820428  
 PDR ADOCK 05000249  
 S PDR

NRC USE ONLY

NAME OF PREPARER

B. Christel

PHONE:

815-942-2920, X-421



Commonwealth Edison

## DEVIATION REPORT

DVR NO. 12 - 3 - 82 - 24  
STA UNIT YEAR NO.

PART 1

TITLE OF DEVIATION

Leak on Condensate Booster Line to Condenser

OCCURRED

4/7/82

1630

DATE

TIME

SYSTEM AFFECTED 3400

PLANT STATUS AT TIME OF EVENT

Condensate

MODE Refuel

PWR(MWT) 0

LOAD(MWE) 0

TESTING

☐ YES☒ NO

DESCRIPTION OF EVENT

A leak was found by Shift Foreman on 1 inch line off of condensate

booster recirculation line to the main condenser.

10 CFR50.72 NRC RED PHONE

☐ YES☒ NO

NOTIFICATION MADE

YES

NO

EQUIPMENT FAILURE

19738

☒ YES☐ NO

WORK REQUEST NO.

RESPONSIBLE SUPERVISOR

F. W. Knollhoff

DATE 4/7/82

PART 2

OPERATING ENGINEER'S COMMENTS

All leakage was contained within the turbine building

floor sumps. The leak was repaired by cutting and capping the 1 inch tap prior to

restart of the condensate system.

☐ EVENT OF PUBLIC INTEREST☐ TECH. SPEC. VIOLATION☐ NON REPORTABLE OCCURRENCE☐ 14 DAY REPORTABLE/T.S.☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.d☐ ANNUAL/SPECL REPORT REQ'D☐ 24-HOUR NRC NOTIFICATION REQ'D

TELEPH M. Jordan (courtesy)

REGION III

4/8/82

DATE

1200

TIME

TELEGM/TELECOPY

REGION III

DATE

TIME

☐ CECO CORPORATE NOTIFICATION MADE

IF ABOVE NOTIFICATION IS PER 10CFR21

☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

TELEPH

F. A. Palmer

CECO CORPORATE OFFICER

4/12/82

DATE

1404

TIME

PRELIMINARY REPORT

COMPLETED AND REVIEWED

Michael Wright

OPERATING ENGINEER

4/12/82

DATE

INVESTIGATED REPORT & RESOLUTION  
ACCEPTED BY STATION REVIEWJack Brunner  
5/3/82Michael Wright  
5-3-82RESOLUTION APPROVED AND  
AUTHORIZED FOR DISTRIBUTIONDouglas Koo  
STATION SUPERINTENDENT

5/3/82

DATE