

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 14 15 25 26 30 37 CAT 38

CONT
 0 1 REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 4 0 2 8 2 8 0 4 2 7 8 2 9
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While performing monthly surveillance DIS 1500-9, it was found that LPCI Differential
 0 3 Pressure Switch 2-261-35B failed to operate on increasing differential pressure (T.S.
 0 4 3.2.B) The safety implications were minimal because the remaining three switches were
 0 5 all operative and would have performed as designed. There was no effect on public
 0 6 health or safety. No previous occurrences noted.
 0 7
 0 8

0 9 SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE S 15 VALVE SUBCODE Z 16
 7 8 9 10 11 12 13 18 19 20
 17 LER/RO REPORT NUMBER 8 2 21 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER G 25 REVISION NO. 0 32 COMPONENT MANUFACTURER G 0 8 0 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause was believed to be wear of a contact point in the mechanical linkage which
 1 1 operates the switch. Switch movement is less than 1/64 inch between open and closed.
 1 2 After minor adjustment of internal "zero" screw, the switch operated. The pressure
 1 3 switch was then adjusted to 55 ± 5 inch dp increasing and repeatability was verified.
 1 4 DIS 1500-9 will continue to be performed. No further action deemed necessary.

1 5 FACILITY STATUS E 28 % POWER 0 9 8 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Tests 32
 7 8 9 10 12 13 44 45 46 80
 1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
 7 8 9 10 11 44 45 80
 1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
 7 8 9 11 12 13 80
 1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
 7 8 9 11 12 80
 1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
 7 8 9 10 80
 2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
 7 8 9 10 80

NAME OF PREPARER

B. A. Schroeder

PHONE:

815-942-2920, X-422



Commonwealth Edison

DEVIATION REPORT

DVR NO. 12 2 82 24
STA UNIT YEAR NO.

PART 1

TITLE OF DEVIATION

LPCI Loop Select dPIS 2-261-35B Failure

OCCURRED

4-2-82

1400

DATE

TIME

SYSTEM AFFECTED 1500

PLANT STATUS AT TIME OF EVENT

LPCI

MODE

Run

PWR(MWT)

2504

LOAD(MWE)

816

TESTING

☒

YES

NO

DESCRIPTION OF EVENT

During DIS 1500-9 the Differential Pressure Indicator Switch 2-261-35B

failed to operate on increasing differential pressure. Adjustment screw was rotated through the entire range with no switch closure. After minor adjustment of internal "zero" screw, switch operated. Switch was adjusted to 55 ± 5 " dp increasing and repeatability verified.

10 CFR50.72 NRC RED PHONE

☐☒

NOTIFICATION MADE

YES

NO

EQUIPMENT FAILURE

☐

YES

☒

NO

WORK REQUEST NO.

RESPONSIBLE SUPERVISOR

Alan R. Zapotocky

DATE

4/2/82

PART 2

OPERATING ENGINEER'S COMMENTS

The other three LPCI loop select dPIS operated properly

during surveillance testing.

☐ EVENT OF PUBLIC INTEREST☐ TECH. SPEC. VIOLATION☐ NON REPORTABLE OCCURRENCE☐ 14 DAY REPORTABLE/T.S.☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.a☐ ANNUAL/SPECL REPORT REQ'D☐ 24-HOUR NRC NOTIFICATION REQ'D

TELEPH

N/A

REGION III

DATE

TIME

TELEGM/TELECOPY

N/A

REGION III

DATE

TIME

☐ CECO CORPORATE NOTIFICATION MADE

IF ABOVE NOTIFICATION IS PER 10CFR21

☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

A.I.R. #

L.E.R. # 82-13/03L-0

TELEPH

F. A. Palmer

4/23/82

1620

CECO CORPORATE OFFICER

DATE

TIME

PRELIMINARY REPORT

COMPLETED AND REVIEWED

John M. Almer

OPERATING ENGINEER

4/23/82

DATE

INVESTIGATED REPORT & RESOLUTION
ACCEPTED BY STATION REVIEWRESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

STATION SUPERINTENDENT