

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I | A | D | A | C | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 1 | 7 | 0 | 4 | 0 | 7 | 8 | 2 | 8 | 0 | 5 | 0 | 3 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During cold shutdown while performing surveillance testing of the main s
03 | team isolation valve-leakage control system (MSIV-LCS), main steam line
04 | pressure switch PS-8404C failed, rendering the MSIV-LCS on the "C" main
05 | steam line inoperable. Following manual system initiation, PS-8404C reis
06 | olates "C" steam line LCS if steam line pressure has not decayed to less
07 | than 5 psig in one minute. System operability required by Tech. Spec. 3.
08 | 7.E. No similar previous occurrences. Problem not generic.

09 | SYSTEM CODE | C | D | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | D | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
EVENT YEAR | 8 | 2 | 21 22 | SEQUENTIAL REPORT NO. | 1 | 2 | 6 | 23 24 25 26 | OCCURRENCE CODE | 0 | 3 | 27 28 29 | REPORT TYPE | L | 30 31 | REVISION NO. | 0 | 32 33
ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 23 24 25 | ATTACHMENT SUBMITTED | N | 26 27 | NPRO-4 FORM SUB. | N | 28 29 | PRIME COMP. SUPPLIER | A | 30 31 | COMPONENT MANUFACTURER | B | 0 | 7 | 0 | 25 26 27 28

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Failure of PS-8404C was due to slight corrosion on its terminal strip wh
11 | ich resulted in a poor electrical connection. The pressure switch and te
12 | rminal strip were cleaned and lubricated to prevent further corrosion. T
13 | he pressure switch was functionally tested satisfactory. No further corr
14 | ective action is planned.

15 | FACILITY STATUS | G | 28 | 4 POWER | 0 | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance Test | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTIVITY RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | PUBLICATION DESCRIPTION | N | 44 | NA | 45 | 8205110646 820503
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ISSUED DESCRIPTION PDR ADDCK 05000331
S PDR

NAME OF PREPARER Kimuel L. Hill

PHONE 319-851-5611

NRC USE ONLY