


$$(7.77)$$
LICENSEE EVENT REPORT

MAY 05 1982

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	N	M	N	P	1	2	0	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		E		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58	

CON'T

REPORT SOURCE: 0 1 7 8

DOCKET NUMBER: L 6 0 5 0 0 0 2 6 3 7 0 4 0 8 8 2 8 0 5 0 8 8 2 9

EVENT DATE: 60 61 68 69 74 75

REPORT DATE: 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While cooling down after reactor scram, lead in control circuitry for outboard
0 3 | shutdown cooling valve, MD-2030, was lifted. after valve was opened. Lifting
0 4 | lead when valve was open and reactor temperature was above 212° F disabled
0 5 | primary containment isolation capability for valve, in violation of Technical
0 6 | Specification 3.7.D.1. Redundant isolation valve was operable. No effect on
0 7 | public health or safety. No previous similar event.
0 8 | _____
7 8 9

SYSTEM CODE C F (11)		CAUSE CODE A (12)		CAUSE SUBCODE A (13)		COMPONENT CODE V A L V O P (14)				COMP. SUBCODE B (15)		VALVE SUBCODE Z (16)	
7 8		9 10		11 12		13 14 15 16 17 18				19 20		21 22	
LER/RO REPORT NUMBER (17)		EVENT YEAR 8 2 (21) (22)		SEQUENTIAL REPORT NO. 0 0 5 (24) (25) (26)		OCCURRENCE / (27)		REPORT TYPE 0 3 (28) (29)		REVISION NO. 0 (30) (31)			
ACTION TAKEN X (18)		FUTURE ACTION A (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)		ATTACHMENT SUBMITTED N (26)		NPRD-4 FORM SUB. N (27)	
33 34		35 36		37 38 39 40		41 42		43 44		45 46		47 48 49 50	
PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER L 2 0 0 (26) (27) (28) (29)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Root cause - special operating procedure written to temporarily solve relaxing
1 1 | torque switch problem was misinterpreted. Corrective action - when lifted lead
1 2 | was discovered, it was immediately re-installed. Also, special operating proce-
1 3 | dure was revised to be more clear. Modification of motor operator to solve
1 4 | relaxing torque switch problem will be installed during next refueling outage.

7		8		9		FACILITY STATUS		% POWER		OTHER STATUS		(30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		(32)		
1	5	D		(28)		0	0	0	(29)	NA				A	(31)	STA Observation				
7	8	9	10	11	12	13	44		45	46	80									

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (32) Z (34) NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

45

LOCATION OF RELEASE (36)

80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	7	0	0	0	37 Z 3E NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	40	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	

10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 [N] 44 NA
8205140218 820507
PDR ADOCK 05000263
S PDR
NRC USE ONLY

NAME OF PREPARER G. L. Carpenter

PHONE: (612) 295-5151

100