

CO² 0 1 REPORT SOURCE L 6 0 5 0 - 0 3 0 2 7 0 3 3 1 8 2 2 0 4 2 8 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVEIT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 2340, hydraulic snubber MSH-168 was found to be leaking hydraulic fluid. It was functionally tested and found to be inoperable. This created an event contrary to Technical Specification 3.7.9.1. Maintenance was initiated and operability was restored on 4/1/82 at 1430. There was no effect upon the health or safety of the general public. This is the seventh report under this Specification.

0	9	Z	Z	11	E	12	C	13	S	U	P	O	R	T	14	D	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
REF NO		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
17		8	2			0	2	9	/	0	3	L				0			
27		21	22	23		24	25	26	27	28	29	30	31	32		33	34	35	36
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
A	X	Z		Z		0	0	0	0	Y		N		A		P	3	1	7
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 6 The cause of this event is attributed to a leaking shaft seal. The snubber was removed,
1 1 repaired, functionally tested satisfactorily and reinstalled. No further corrective
action is deemed necessary.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	G	28	0	0	0	29	B	31	Operator observation
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE				
1	6	Z	33	Z	34	NA	NA			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	NA		
PERSONNEL INJURIES		NUMBER		DESCRIPTION						
1	8	0	0	0	40	NA				
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION						
1	9	Z	42	NA						
PUBLICITY		ISSUED		DESCRIPTION						
2	0	N	44	NA						

8205180489

NRC USE ONLY

Supplementary Information

Report No.: 50-302/82-029/03L/0

Facility: Crystal River Unit 3

Report Date: April 28, 1982

Occurrence Date: March 31, 1982

Identification of Occurrence:

Hydraulic snubber (MSH-168) was inoperable contrary to Technical Specification 3.7.9.1.

Conditions Prior to Occurrence:

Mode 3 - hot standby (0%).

Description of Occurrence:

At 2340, hydraulic snubber (MSH-168) was found leaking. The hydraulic snubber was removed and functionally tested. It was found to be inoperable. Maintenance was initiated and operability was restored at 1430 on 4/1/82.

Designation of Apparent Cause:

The cause of this event is attributed to a leaking shaft seal.

Analysis of Occurrence:

The plant was in hot standby at the time of discovery. There was no effect upon the health or safety of the general public.

Corrective Action:

The hydraulic snubber (MSH-168) shaft seal was replaced, the snubber was functionally tested satisfactorily, and reinstalled. No further corrective action is deemed necessary.

Failure Data:

This is the seventh report under this Specification.

/rc