

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	-	0	3	2	4	7	0	4	0	9	8	2	8	0	5	0	7	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During plant operation, it was discovered that while performing a plant modification

0 3 to relocate hydraulic snubber, 2-E11-107SS573, located on the keep fill piping

0 4 immediately downstream of the division 1 RHR/LPCI isolation valve, 2-E11-F082A, it

0 5 had been removed and reinstalled without operations being notified. This event did

0 6 not affect the health and safety of the public.

0 7

0 8 Technical Specifications 3.7.5, 6.9.1.9b

7 8 9 80

0	9	S	H	11	A	12	E	13	S	U	P	O	R	T	14	D	15	Z	16
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----

7 8 9 10 11 12 13 18 19 20

17	8	2	---	0	7	0	/	0	3	L	---	0
----	---	---	-----	---	---	---	---	---	---	---	-----	---

21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 A 25 B 2 0 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 While performing work required by the modification a breakdown in communication

1 1 occurred between the concerned plant construction personnel. As a result,

1 2 the snubber was removed without the required operations notification. The involved

1 3 person has been counseled to be aware of the necessity of possessing required LCOs

1 4 prior to removing hydraulic snubbers.

7 8 9 80

1	5	E	28	0	8	2	29	NA	30	A	31	Maintenance Observation	32
---	---	---	----	---	---	---	----	----	----	---	----	-------------------------	----

7 8 9 10 12 13 44 45 46 80

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

7 8 9 10 11 44 45 80

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

7 8 9 11 12 13 44 80

1	8	0	0	0	40		41	NA	42
---	---	---	---	---	----	--	----	----	----

7 8 9 11 12 44 80

1	9	Z	42		43	8205180665	44	NA	45
---	---	---	----	--	----	------------	----	----	----

7 8 9 10 11 12 44 80

2	0	N	44		45		46	NA	47
---	---	---	----	--	----	--	----	----	----

7 8 9 10 11 12 44 80

NAME OF PREPARER: M. J. Pastva, Jr.

PHONE: 919-457-9521

LER ATTACHMENT - RO #2-82-70

Facility: BSEP Unit No. 2

Event Date: April 9, 1982

During plant operation, while performing a plant modification involving the relocation of hydraulic snubber 2-Ell-107SS573, the snubber was removed without notifying Operations so that an LCO could be taken out on the system.

This event occurred as a result of a breakdown in communications between the plant Construction personnel performing the work. One of the two personnel involved, the one responsible for relocating the snubber and obtaining the LCO, assumed the other person, who was responsible for installing the new snubber supports, had completed the necessary documentation for the LCO when the supports were installed. Discovery of this event was made following completion of the modification work when plant Maintenance personnel's surveillance of the work revealed the subject snubber was leaking hydraulic fluid from its seals.

From conversation with the involved plant Construction personnel, it was then determined that the snubber relocation had been performed without the required LCO. Plant Operations was immediately notified of this discovery and an LCO was issued to remove, repair and test the snubber. Upon removal, the subject snubber was functionally tested and found satisfactory. To facilitate a timely return of the snubber to service, it was replaced with another rebuilt, compatible snubber which had been satisfactorily tested for operability prior to installation.

As a result of this event, the responsible plant Construction person has been counseled to be aware of the importance of strict adherence to LCO requirements involving the removal of hydraulic snubbers. In addition, "hold points" will henceforth be used for all hydraulic snubber modification work, requiring a review of the involved work by the Operations Shift Foreman prior to commencement of the work.