

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LER No.: 50-366/1982-033
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1982-033

With the plant in refuel and while performing HNP-2-3410, RCIC Steamline Differential Pressure Instrument Functional Test and Calibration, 2E51-N017, was found to actuate at positive 105 inches of water differential pressure. Technical Specifications Table 3.3.2-2 requires actuation at less than or equal to 300 percent of rated steam flow which is equivalent to 111 inches of water dP minus 10 inches of water head correction. RCIC Steamline dP Switches 2E51-N017 and 2E51-N018 are not required to be operable in the refuel mode; however, there existed a period of time after the last regular surveillance, which was done on January 28, 1982, during power operation and before entering the condition which they are not required to be operable that the setpoint of 2E51-N017 could have been out of allowable limits. Redundant switch 2E51-N018 was operable. Neither plant operation nor the public's health and safety were affected by this event. This is a non-repetitive event.

The cause of this event has been attributed to setpoint drift. The switch, a Barton Model 288A, was immediately recalibrated per HNP-2-3410 and returned to service.

CONFIRMATION STATEMENT

For Document 50-366/1982-033 Lat O
(Description of Document)

I have checked the statements made in this document and, to the best of my knowledge, the statements made in this response are accurate.

E. D. Heery
(Signature)

5-6-82
(Date)

REGULATORY COMPLIANCE REVIEW
DOCUMENT # <u>1ER 2-82-33</u>
CHANGES NEEDED () Yes () No
IF YES, SEE COMMENTS
COMMENTS:
REVIEWED BY: <u>TKS</u>
DATE: <u>5/10/82</u>