

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT
01 REPORT SOURCE L 6 0 5 0 0 0 0 3 6 9 7 0 4 0 1 8 2 8 0 4 3 0 8 2 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in mode 1, radiation monitors EMF-31 (conventional waste) and EMF-33 (con-
03 densate air ejector) experienced loss of power resulting from a tripped circuit
04 breaker (which is the common power supply to them and EMF-46 (component cooling
05 water)), and were declared inoperable (per T.S.3.3.3.8 and 3.3.3.9) after the
06 power breaker would not reset. This is reportable per T.S.6.9.1.13(b), and re-
07 quired periodic sampling per the action statements. Because of the sampling and
08 availability of a redundant monitor, health and safety of the public were unaffected.

09 SYSTEM CODE M C 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
17 LER/RP REPORT NUMBER 8 2 21 EVENT YEAR 8 2 22 SEQUENTIAL REPORT NO. 0 2 8 23 OCCURRENCE CODE 0 3 24 REPORT TYPE L 25 REVISION NO. 0 26
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER G 0 6 3 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 EMF-46 was identified as causing the breaker to trip (a direct short across the
11 "power" bulb was discovered) and was isolated from the power circuit until it
12 was repaired. Power was restored to EMF '31 and 33 within 4 hours and they were
13 returned to service. The bulb was replaced and EMF-46 returned to service the
14 next day.

15 FACILITY STATUS B 28 % POWER 0 5 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Annunciator 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

NAME OF PREPARER Phillip B. Nardoci PHONE: 704- 373-7432