

## CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58	

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 3 2 1 7 0 2 0 5 8 2 8 0 2 2 5 8 2 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While the plant was in startup mode at 5 MWt, 1T47-R612, Drywell Temperature  
0 3 | Recorder, was found to be inoperable. Tech Specs Table 3.2-11 requires  
0 4 | two operable channels. Redundant recorder, 1T47-R611, was also inop  
0 5 | placing the plant in a 30 day LCO. Plant operation was placed in a 7 day  
0 6 | LCO as a result of this event. The health and safety of the public was  
0 7 | not affected. This is a non-repetitive event.  
0 8 |

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
0	9	I	D	E		E		I	N	S	T	R	U	R		Z	
7	8	9	10	11	12	12	13	13	14	15	16	17	18	19	20		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		8	2		008		03	L		0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z		Z		0000		Y		N		A		T	039		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the event has been attributed to component failure. The

1 1 | failure was due to a broken micro switch. The switch was replaced and

1 2 | the recorder was returned to service.

1 3 |

1 4 |

7 R 9

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	C	28	0	0	0	29	NA				B	31	Operator observation					
ACTIVITY				CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA				NA									
PERSONNEL EXPOSURES				DESCRIPTION															
1	7	0	0	0	37	Z	38	NA											
PERSONNEL INJURIES				DESCRIPTION															
1	8	0	0	0	40	NA													
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION															
1	9	Z	42	NA															
PUBLIC				ISSUED				NRC USE ONLY											
2	0	N	44	8205210273 820225 PDR ADOCK 05000321 S PDR															

NAME OF PREPARER R. T. Nix, Supt. of Maint.

912-367-7781

LER No.: 50-321/1982-008.  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket No.: 50-321

Narrative Report  
for LER 50-321/1982-008.

While the plant was in startup mode at 5 Mwt, 1T47-R612 (Drywell Temperature Recorder, was found to be inoperable. Tech Specs Table 3.2-11 requires two operable channels. Redundant recorder, 1T47-R611, was also inop placing the plant in a 30 day LCO. Plant operation was placed in a 7 day LCO as a result of this event. The health and safety of the public was not affected. This is a non-repetitive event.

The cause of the event has been attributed to component failure. The failure was due to a broken micro switch. The switch was replaced and the recorder was returned to service.