

LICENSEE EVENT REPORT

EXHIBIT A

| CONTROL BLOCK: | | | | | | | | | | (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|---|--|--|--|--|--|--|--|--|--|
| S C N E E 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 <small>LICENSE CODE DOCKET NUMBER EVENT DATE REPORT DATE</small> | | | | | | | | | | | | | | | | | | | |
| REPORT SOURCE | | | | | | | | | | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES | | | | | | | | | |
| On April 28, 1982, during the final Reactor Building inspection, one vertical tendon in the secondary shield wall was found broken. Subsequent detailed inspection of Units 2 and 3 found one additional failed tendon in Unit 2 and some rusted vertical tendons in Units 2 and 3. The primary structural integrity of the wall system and its ability to perform its design function are considered to be intact; thus, this event did not have a significant effect on the health and safety of the public. | | | | | | | | | | | | | | | | | | | |
| SYSTEM CODE X X | | | | | | | | | | CAUSE CODE E | | | | | | | | | |
| CAUSE SUBCODE B | | | | | | | | | | COMPONENT CODE X X X X X X X | | | | | | | | | |
| COMP. SUBCODE Z | | | | | | | | | | VALVE SUBCODE Z | | | | | | | | | |
| LER/NO REPORT NUMBER 8 2 | | | | | | | | | | REVISION NO. 0 | | | | | | | | | |
| ACTION TAKEN A G C A 0 4 5 Y N L P | | | | | | | | | | EFFECT ON PLANT C | | | | | | | | | |
| SHUTDOWN METHOD A | | | | | | | | | | ATTACHMENT SUBMITTED Y | | | | | | | | | |
| HOURS 0 4 5 | | | | | | | | | | NPRO-4 FORM SUB. N | | | | | | | | | |
| PRIME COMP. SUPPLIER L | | | | | | | | | | COMPONENT MANUFACTURER P 3 6 2 | | | | | | | | | |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS | | | | | | | | | | | | | | | | | | | |
| The apparent cause of this occurrence was stress corrosion of the post-tensioning wires near the stressing washers caused by water in the bottom of the vertical tendon sheaths. Defective tendons will be replaced and bottom grease caps modified to allow water drainage. A tendon surveillance program will be implemented | | | | | | | | | | | | | | | | | | | |
| FACILITY STATUS G | | | | | | | | | | OTHER STATUS Hot shutdown | | | | | | | | | |
| % POWER 0 0 0 | | | | | | | | | | DISCOVERY DESCRIPTION Operator observation | | | | | | | | | |
| ACTIVITY RELEASED Z | | | | | | | | | | LOCATION OF RELEASE NA | | | | | | | | | |
| PERSONNEL EXPOSURES 1 2 0 E | | | | | | | | | | Maintenance - 6.7 Rem | | | | | | | | | |
| PERSONNEL INJURIES 0 0 0 | | | | | | | | | | NA | | | | | | | | | |
| LOSS OF OR DAMAGE TO FACILITY TYPE Z | | | | | | | | | | NA | | | | | | | | | |
| PUBLICITY ISSUED N | | | | | | | | | | NRC USE ONLY | | | | | | | | | |

8205210347 820512
PDR ADCK 05000270
S PDR

J. F. Kutzer

PHONE: (704) 373-7139