

LICENSEE EVENT REPORT

CONTROL BLOCK:

| | | | | | |
|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 | 6 |
|---|---|---|---|---|---|

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|---|
| 0 | 1 | M | D | C | C | N | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|---|

7 8 9 14 15 25 26 30 37 CAT 58

CON'T

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 8 | 7 | 0 | 4 | 1 | 7 | 8 | 2 | 8 | 0 | 5 | 1 | 4 | 8 | 2 | 9 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 0739 during normal operation, CEA 21 dropped into the core after

0 3 electricians inadvertently disconnected power from it (T.S. 3.1.3.1).

0 4 This resulted in pressurizer level deviation from programmed level by

0 5 greater than +/- 5% (T.S. 3.4.4.b). At 0741 CEA 20 also dropped into the

0 6 core at which point, the reactor was manually tripped. Power was immedi-

0 7 ately restored to CEA 21 and 20 restoring their operability. All other

0 8 CEA's remained operable during this event. Repetitive events: none.

7 8 9 80

| | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|----|---|----|---|----|---|---|---|---|---|---|----|---|----|---|----|
| 0 | 9 | R | B | 11 | A | 12 | C | 13 | X | X | X | X | X | X | 14 | Z | 15 | Z | 16 |
|---|---|---|---|----|---|----|---|----|---|---|---|---|---|---|----|---|----|---|----|

7 8 9 10 11 12 13 18 19 20

| | | | | | | | | | | | | |
|----|---|---|--|---|---|---|---|---|---|---|--|---|
| 17 | 8 | 2 | | 0 | 1 | 8 | / | 0 | 3 | L | | 0 |
|----|---|---|--|---|---|---|---|---|---|---|--|---|

21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
H 18 G 19 A 20 B 21 0 0 1 3 Y 23 N 24 N 25 Z 9 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for this event was personnel error. Electricians began work on

1 1 Unit 2 CEA's instead of the assigned Unit 1 equipment. The lead person

1 2 on the job was interviewed by supervision to assess the cause and in-

1 3 structed in proper means of determining job scope. Also, a revision to

1 4 an administrative instruction will be made to prevent recurrence.

7 8 9 80

| | | | | | | | | | | | | |
|---|---|---|----|---|---|---|----|----|---|----|----------------------|----|
| 1 | 5 | E | 28 | 1 | 0 | 0 | 29 | NA | A | 31 | Operator Observation | 32 |
|---|---|---|----|---|---|---|----|----|---|----|----------------------|----|

7 8 9 10 12 13 44 45 46 80

| | | | | | | | | | | |
|---|---|---|----|---|----|----|----|----|----|----|
| 1 | 6 | Z | 33 | Z | 34 | NA | NA | 35 | NA | 36 |
|---|---|---|----|---|----|----|----|----|----|----|

7 8 9 10 11 44 45 80

| | | | | | | | | | |
|---|---|---|---|---|----|---|----|----|----|
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |
|---|---|---|---|---|----|---|----|----|----|

7 8 9 11 12 13 80

| | | | | | | | |
|---|---|---|---|---|----|----|----|
| 1 | 8 | 0 | 0 | 0 | 40 | NA | 41 |
|---|---|---|---|---|----|----|----|

7 8 9 11 12 80

| | | | | | | | | | | |
|---|---|---|----|------------|--------|-----|-------|----------|-----|----|
| 1 | 9 | Z | 42 | 8205240352 | 820514 | PDR | ADOCK | 05000318 | PDR | 43 |
|---|---|---|----|------------|--------|-----|-------|----------|-----|----|

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

| | | | | | |
|---|---|---|----|----|----|
| 2 | 0 | N | 44 | NA | 45 |
|---|---|---|----|----|----|

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER J.W. Raynor

PHONE: 301-269-4713

| | |
|-------------------|-------------|
| LER NO. | 82-82-18/3L |
| DOCKET NO. | 50-318 |
| LICENSE NO. | DPR-69 |
| EVENT DATE | 04-17-82 |
| REPORT DATE | 05-14-82 |
| <u>ATTACHMENT</u> | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

This event was caused by personnel error. The electricians worked on Unit 2's CEAs but were assigned to work on Unit 1's CEA. Because he had recently worked on a CEA power supply problem in Unit 2, the lead electrician believed the work assigned was continued work pertaining to Unit 2. He, therefore, carried out instructions given for working on the shutdown Unit 1's CEA Coil Power Programmer Panel. (The unit's Coil Power Programmer Panels are located in different rooms.)

The lead electrician has been interviewed by several levels of supervision to assess the cause and be instructed in the proper means of determining the job scope. In addition, a revision to an administrative instruction will be made to provide direction on how jobs which are not continuous are to be reviewed or redefined.