

• CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

② ③ ④ ⑤

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During a maintenance activity the Cable Riser Shaft Water Spray Fire
03 | Protection System was inadvertantly activated. The cable tray fire
04 | retardant barrier material was damaged by the water. No other equipment
05 | was damaged. No safety systems important to plant safety were affected.
06 | There was no effect upon public health and safety.
07 |
08 |

7 8 9

0 9
7 8

SYSTEM CODE
A B (11)
9 10

CAUSE CODE
A (12)
11

CAUSE SUBCODE
C (13)
12

COMP. SUBCODE
8 (15)
19

VALVE SUBCODE
8 (16)
20

SEQUENTIAL REPORT NO.
0 0 7 (17)
24 26

OCCURRENCE CODE
0 3 (18)
28 29

REPORT TYPE
L (19)
30

REVISION NO.
0 (20)
32

ACTION TAKEN
B (18)
33

FUTURE ACTION
F (19)
34

EFFECT ON PLANT
8 (20)
35

SHUTDOWN METHOD
8 (21)
36

HOURS
0 0 0 0 (22)
37 40

ATTACHMENT SUBMITTED
Y (23)
41

NPRD-4 FORM SUB.
N (24)
42

PRIME COMP. SUPPLIER
8 (25)
43

COMPONENT MANUFACTURER
8 8 8 8 (26)
44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The Fire Spray System was initiated due to a misunderstanding between
1 1 | personnel, allowing maintenance to begin on a manual switch before the
1 2 | Spray System Block Valve was closed. Alternate manual switches are being
1 3 | reviewed to determine if two-positive action type switches can be
1 4 | installed.

| | | | | | | | | | | | | | | | |
|-------------------------------|---|---|---------------------|----|----|--------------------|----|-----------------|---------------------|----|----|-----------------------|----------------------|----|--|
| FACILITY STATUS | | | % POWER | | | OTHER STATUS | | | METHOD OF DISCOVERY | | | DISCOVERY DESCRIPTION | | | |
| 1 | 5 | B | 28 | 0 | 0 | 0 | 29 | Initial startup | | | A | 31 | Operator Observation | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |
| ACTIVITY CONTENT | | | RELEASED OF RELEASE | | | AMOUNT OF ACTIVITY | | | LOCATION OF RELEASE | | | | | | |
| 1 | 6 | B | 33 | B | 34 | NA | | | NA | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |
| PERSONNEL EXPOSURES | | | NUMBER | | | TYPE | | | DESCRIPTION | | | | | | |
| 1 | 7 | 0 | 0 | C | 37 | B | 38 | NA | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |
| PERSONNEL INJURIES | | | NUMBER | | | DESCRIPTION | | | | | | | | | |
| 1 | 8 | 0 | 0 | 0 | 40 | NA | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |
| LOSS OF OR DAMAGE TO FACILITY | | | TYPE | | | DESCRIPTION | | | | | | | | | |
| 1 | 9 | B | 42 | NA | | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |
| PUBLICITY | | | ISSUED | | | DESCRIPTION | | | | | | NRC USE ONLY | | | |
| 2 | 0 | N | 44 | NA | | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | |

NRC USE ONLY

8204160215 820407
PDR ADCK 05000361
S PDR

H. B. Ray

PHONE: (714) 492-7700