

A L J M F 1 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 1

REPORT SOURCE L 0 5 0 0 0 3 4 8 0 3 0 7 8 2 0 4 0 2 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
At 1030 on 3/07/82 the instrumentation loop associated with steam flow transmitter FT-476 was declared inoperable when the steam flow transmitter failed low. Tech. Spec. 3.3.1.1, in part, requires FT-476 to be operable. Tech. Spec. 3.3.1.1 action statement requirements were met. The health/safety of the public was not affected.

SYSTEM CODE I A (11) CAUSE CODE E (12) CAUSE SUBCODE G (13) COMPONENT CODE I N S T R U (14) COMP SUBCODE T (15) VALVE SUBCODE Z (16)
EVENT HEAD 8 2 (17) SEQUENTIAL REPORT NO 0 0 8 (24) OCCURRENCE CODE 0 3 (28) REPORT TYPE L (30) REVISION NO 0 (32)
ACTION TAKEN A (33) EFFECT ON PLANT Z (34) SHUTDOWN METHOD Z (35) HOURS 0 0 0 0 (37) ATTACHMENT SUBMITTED N (41) NRC FORM SUB N (42) PRIME COMP SUPPLIER N (43) COMPONENT MANUFACTURER W 1 2 0 (44)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
This event is attributable to a faulty power supply card. The card was replaced and following calibration of the new card, FT-476 instrumentation loop was returned to service at 1900 on 3/07/82.

FACILITY STATUS C (28) % POWER 0 2 2 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION Operational Event (32)
ACTIVITY RELEASED OR RELEASE Z (33) Z (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)
PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)
PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)
LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)
PUBLICITY N (44) DESCRIPTION NA (45)