

ALJMF1 00-00000-00041111  
LICENSEE CODE 14 15 LICENSE NUM 25 26 LICENSE TYPE 30 31 CAT 56

REPORT SOURCE L 05000348 031282 040282  
DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
At 0220 on 3/12/82 the instrumentation loop associated with pressurizer pressure transmitter PT-455 was declared inoperable when the pressure transmitter failed low. Tech. Spec. 3.3.1.1 and 3.3.1.2, in part, require PT-455 to be operable. Tech. Spec. action statement requirements were met. The health/safety of the public was not affected.

SYSTEM CODE I A (11) CAUSE CODE E (12) CAUSE SUBCODE G (13) COMPONENT CODE INSTRU (14) COMP SUBCODE T (15) VALVE SUBCODE Z (16)  
EVENT YEAR 8 2 (17) SEQUENTIAL REPORT NO. 0 0 9 (18) OCCURRENCE CODE 0 3 (19) REPORT TYPE L (20) REVISION NO. 0 (21)  
ACTION TAKEN A (22) Z (23) EFFECT ON PLANT Z (24) SHUTDOWN METHOD Z (25) HOURS 0 0 0 0 (26) ATTACHMENT SUBMITTED N (27) NRC FORM SUB. N (28) PRIME COMP SUPPLIER N (29) COMPONENT MANUFACTURER W 1 2 0 (30)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
This event is attributable to a faulty power supply card. The card was replaced with a new calibrated card and PT-455 instrumentation loop was returned to service at 0420 on 3/12/82.

FACILITY STATUS E (31) % POWER 0 4 4 (32) OTHER STATUS NA (33) METHOD OF DISCOVERY A (34) DISCOVERY DESCRIPTION Operational Event (35)  
ACTIVITY CONTENT RELEASED OR RELEASE Z (36) Z (37) AMOUNT OF ACTIVITY NA (38) LOCATION OF RELEASE NA (39)  
PERSONNEL EXPOSURES NUMBER 0 0 0 (40) TYPE Z (41) DESCRIPTION NA (42)  
PERSONNEL INJURY NUMBER 0 0 0 (43) DESCRIPTION NA (44)  
LOSS OF OR DAMAGE TO FACILITY TYPE Z (45) DESCRIPTION NA (46)  
PUBLICITY ISSUED N (47) DESCRIPTION NA (48)