

4 1 A L J M F 2 7 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32
8 REPORT SOURCE L 6 0 5 0 0 0 3 6 4 7 0 3 1 6 8 2 9 0 4 0 2 8 2
63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 At 1435 on 3/16/82 the 120V AC vital bus "B" was deenergized when inverter 2B tripped.
3 Tech. Spec. 3.8.2.1, in part, requires the "B" bus and inverter 2B to be operable and
4 energized. Tech. Spec. 3.8.2.1 action statement requirements were met. The health/
5 safety of the public was not affected.

6
7
8
9

0 9
8 9
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
E B 11 E 12 F 13 G E N E R A 14 F 15 Z 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO
8 2 0 1 1 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC FORM SUB PRIME COMP SUPPLIER COMP. MFG MANUFACTURER
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 22 N 23 Z 24 Z 25 Z 26 9 9 9
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

0 This event occurred when inverter 2B failed due to a blown fuse in the voltage
1 regulator circuit. Following replacement of the fuse, bus "B" was returned to service
2 at 1710 on 3/16/82.
3
4

5
6
7
8
9
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 31
E 28 0 3 3 29 NA A 31 Operational Event
ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
RELEASED OR RELEASE Z 32 Z 33 NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 37 NA
0 0 0 34 Z 38
PERSONNEL INJURIES NUMBER DESCRIPTION 39 NA
0 0 0 40
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 41 NA
Z 42
PUBLIC POWERED DESCRIPTION 43 NA
N 44
NRC USE ONLY
68 69