




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

April 15, 1982  
RBG-12,430  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station-Unit 1  
Docket No. 50-458

On March 16, 1982, Gulf States Utilities (GSU) informed Region IV that a deficiency reported on February 16, 1982, had been determined to meet the reporting requirements of 10CFR50.55(e). The deficiency was a lack of redundant sensing current transformers for overcurrent protection in certain 4.16KV switchgear.

The attachment to this letter provides information required by 10CFR50.55(e) paragraph (3). This concludes GSU's reporting of this deficiency.

Sincerely,

J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

JEB/LAE/kt

Attachment

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8204230 470

S



IE-27  
11

April 15, 1982  
RBG- 12,430

## ATTACHMENT

### Background and Description of Problem

A review of FSAR Section 8.3.1.1.4.3 (Containment Electrical Penetration Protection) was conducted against the requirements of Regulatory Guide 1.63, Revision 2. This review identified an area of concern with regard to the final design of Class 1E electrical penetration protective system. The lack of channel independence and a single failure situation in the 4.16-KV metal-clad switchgear serving the reactor recirculation pump motor through a Class 1E penetration, is a deficiency. Specifically, two redundant Class 1E circuit breakers were provided with only one set of sensing current transformers and associated relays used to trip both redundant breakers. A persisting overcurrent condition could cause damage to the electrical penetration.

### Safety Implications

The 4.16-KV metal-clad switchgear deficiency is a significant deficiency in final design such that the design does not conform to the criteria in the FSAR; had it remained uncorrected, it could have adversely affected the safety of operations.

### Corrective Action

Procurement of a second current transformer, associated relays, and redundant control circuitry is underway. A second set of current transformers and associated relays will be added to ensure that the 4.16-KV switchgear design conforms to the FSAR and Regulatory Guide 1.63, Revision 2. The 4.16-KV switchgear will be corrected prior to delivery to the jobsite.

Pursuant to standard engineering practices, Stone & Webster Engineering Corporation's River Bend Station Project Electrical Engineering Department is reviewing electrical one-line diagrams to ensure proper protection of electrical penetrations. It was this review that identified the above-stated problem. Specific corrective action for this problem, includes revising one-line Diagram No. 12210-EE-1N-3 and Purchase Order No. RBS-242.521 to provide for the addition of redundant overcurrent protection equipment for the 4.16-KV switchgear. One-line Diagram No. 12210-EE-1N-3 will be reissued with corrections by April 30, 1982. The one-line diagram review, initiated in December 1981 and still underway, will be completed by June 1, 1982.