

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5
7	8	14						15	25										26	30					57	CAT	58		
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE									

REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 3 1 6 8 2 8 0 4 1 5 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

02 | INTERIM REPORT: During normal operation, personnel noted two (2) damaged

snubbers on the fuel pool cooling to RHR return line. Both snubbers are required

to be operable by TS 3.6.1.1 and were replaced with operable spares within the

72 hours allowed by TS 3.6.I.2. No significant hazard existed.

0	6
---	---

07 | Page

Page 1 of 1

7 8 9

0 9

SYSTEM CODE C F 11

CAUSE CODE X 12

CAUSE SUBCODE Z 13

COMPONENT CODE S U P P O R T 14

COMP. SUBCODE D 15

VALVE SUBCODE Z 16

17	LER/RO REPORT NUMBER	EVENT YEAR	REPORT NO.	CODE	TYPE	NO.			
		8 2	0 1 2	0 3	L	0			
		21 22	23 24 25 26	27 28 29	30 31	32			
	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
	C	X	Z	Z	0 0 0 0	N	N	A	S 4 2 0
	13 14 15 16 17 18 19	20	21	22	23 24 25 26 27 28 29 30 31 32	33 34 35 36 37 38 39 40 41 42 43 44 45 46 47	48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100	101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200	201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause of the damage to the snubbers has not been determined. Inspection of the

pipe and associated hangers and other pipe supports did not reveal evidence of

_____ damage. Investigation into the cause and preventing recurrence continues.

7 8 9 METHOD OF

FACILITY STATUS (1) 5 (2) E (28) % POWER (3) 0 (4) 7 (5) 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) A (32) DISCOVERY DESCRIPTION (32) Personnel Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	(37)	Z	(38)	NA	(39)

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50						
PERSONNEL INJURIES																																																	
NUMBER										DESCRIPTION (41)																																							

1 2 0 0 0 40 NA 8204265 80

LOSS OF OR DAMAGE TO FACILITY		(43)	8204260199
TYPE	DESCRIPTION		

1	9	Z	(42)	NA
---	---	---	------	----

7 8 9 10

PUBLICITY
ISSUED - DESCRIPTION (45) NRC USE ONLY

[illegible]

7 8 9 10 68 69 80

NRC USE ONLY

(315) 342-3840 X207