

July 6, 1982

Mr. R. C. Haynes, Director
Region I
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUBJECT: LICENSEE EVENT REPEAT PROMPT NOTIFICATION

Dear Mr. Haynes:

Reference: Docket No. 50-277
Peach Bottom Unit 2
Tech. Spec. Ref.: Table 3.2.A
Report No.: 2-82-15/1P
Occurrence Date: July 3, 1982
Facility: Peach Bottom Atomic Power Station
RD 1, Delta, PA 17314

IDENTIFICATION OF OCCURRENCE:

The 'D' main steam line flow transmitter (FT 51D) and one of four 'D' main steam line high flow transmitters (dPIS 119C) were found with open equalizing valves.

CONDITION PRIOR TO OCCURRENCE:

Unit operating at approximately 34%.

APPARENT CAUSE OF THE OCCURRENCE:

Operator observation led to the discovery of the open equalizing valves. Investigation is still underway to determine the cause of the event.

8207220401 820706
PDR ADOCK 05000277
S PDR

SIGNIFICANCE OF THE OCCURRENCE:

The open equalizing valves cause both legs of dPIS 119A thru D to be equalized as well as both legs of FT 51D. This condition could prevent a high flow signal to PCIS from a break in the 'D' main steam line.

IE29

Page 2


CORRECTIVE ACTIONS:

Immediate steps were taken to verify proper valving of instruments by performance of ET 8.0-2 (Instrument Valve C.O.L.).

FUTURE CORRECTIVE ACTION:

Future actions will be determined pending investigation.

Very truly yours,



R. S. Melachman, II

RS:ljm