

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
NEW YORK WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06141-0270
(203) 665-5000

June 22, 1990
MP-90-614

Docket No. 50-423
Re: 10CFR50.36

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

- References: (1) Special Report, Stephen E. Scace Letter (MP-13448) to U.S. Nuclear Regulatory Commission, Millstone Nuclear Power Station, Unit No. 3, Malfunctioning Loose Parts Monitor Channels, dated August 25, 1989
- (2) Special Report, Stephen E. Scace/Carl H. Clement Letter (MP-13906) to U.S. Nuclear Regulatory Commission, Millstone Nuclear Power Station, Unit No. 3, Malfunctioning Loose Parts Monitor Channels, dated January 2, 1990

Gentlemen:

Millstone Nuclear Power Station, Unit No. 3
Malfunctioning Loose Parts Monitor Channel

This Special Report is being submitted pursuant to Millstone Unit 3 Technical Specification 3.3.3.8.a: Loose Part Detection System. Plant Technical Specification 3.3.3.8.a requires a Special Report be submitted to the NRC 10 days following one or more channels of the Loose Part Detection System inoperable for more than 30 days. This Special Report also supplements the August 25, 1989 and January 2, 1990 Special Reports on Malfunctioning Loose Parts Monitor Channels (referenced above).

On July 16, 1989 with the plant in Mode 1, at 48% power, 2250 psia, and 586 degrees Fahrenheit, two of twelve Loose Parts Monitor (LPM) channels were declared inoperable. Data analysis verified that loose part impacts were not occurring. Further investigation revealed that the alarms were caused by malfunctions in LPM equipment located inside the containment building. For this reason, corrective actions were scheduled for the next reactor Cold Shutdown period.

Cent No P67145080A

9007030104 900622
PDR ADOCK 05000423
S PDC

IF22

1/0

Millstone Unit 3 was in Cold Shutdown from November 29, 1989 to December 5, 1989 to replace the "C" Pressurizer Code Safety Valve, as reported by Licensee Event Report 89-031-00. During this time, the malfunctioning LPM channels were investigated further and exact locations of failed components were identified. Replacement of the components would have required extending the outage by several days to remove and reinstall mirror insulation on the reactor head and the affected steam generator, but would not have increased plant safety since redundant LPM channels monitoring these locations were operating satisfactorily. For these reasons, the component replacement was scheduled for the next refueling outage.


Millstone Unit 3 was shutdown from May 10, 1990 to May 20, 1990 to perform improvements to the intake structure. On May 16, 1990 the malfunctioning channels were repaired and returned to service.

On May 19, 1990 with the plant in Mode 3 (Hot Standby), 0% power, 585 degrees Fahrenheit, and 2250 psia, one LPM channel was placed out of service was alarming continually but data analysis data showed there were no associated impact events. This channel is not one of the two which were returned to service on May 16, 1990. The malfunctioning channel has a redundant channel which is operating normally. Other channels are not affected. To prevent valid loose part impact alarms from being masked, the malfunctioning channel has been turned off. This channel will be repaired during the next refueling outage.

The licensee contact for this special report is Robert Conway, who may be contacted at (203) 444-5442.

Very Truly Yours,

NORTHEAST NUCLEAR ENERGY COMPANY


Stephen E. Scace
Director, Millstone Station

SES/RDC:bjc

cc: T. T. Martin, Region I, Administrator
W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2, and 3
D. H. Jaffe, NRC Project Manager, Millstone Unit No. 3