

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME		LIC. # NUMBER		LICENSE TYPE		EVENT TYPE	
01	M	N	M	N	P	1	0
7	8	9	14	15	25	26	32
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER	
01	CONT		T	L	0	5	0
7	8	57	58	59	60	61	68
EVENT DATE		REPORT DATE					
0	9	1	0	7	7	1	1
69	74	75	80	80	80	80	80

EVENT DESCRIPTION

02	While performing local leak rate tests, the "A" outboard MSIV, AO-2-86A, was found	80
03	leaking in excess of the technical specification acceptance criteria. Redundant	80
04	isolation valve leaking at a rate of 14.64 SCFH. Previous similar events. Valve	80
05	seats lapped (M-RO-77-24-7)	80
06		80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE		PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER		VIOLATION	
07	C	D	E	V	A	L	V	E	X	A	5
7	8	9	10	11	12	13	14	15	16	17	43

CAUSE DESCRIPTION

08	Atwood and Morrill Co. 18-inch, Y type globe valve, drawing 20786-H. Failed leak	80
09	rate test due to plug being slightly out of round. Seats lapped and valve retested	80
10	satisfactory.	80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	H	0	0	0	NA	B	NA		
7	8	9	10	11	12	13	44	45	46
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA				NA		
7	8	9	10	11	12	13	44	45	46

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
7	8	9	12

OFFSITE CONSEQUENCES

15	NA	80
----	----	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
7	8	9	10

PUBLICITY

17	NA	80
----	----	----

ADDITIONAL FACTORS

18	NA	80
----	----	----

19		80
----	--	----

NAME P A Tobin

PHONE 612/295-5151

GPO 881-667

9102130570 771118
CF ADOCK 05000263
CF