



Commonwealth Edison
Braidwood Nuclear Power Station
Route #1, Box 84
Braceville, Illinois 60407
Telephone 815/458-2801

September 27, 1993
BW/93-0254

Mr. J. B. Martin
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: CECO Braidwood Unit 1 Third Outage
Steam Generator Inservice Inspection Results
NRC Docket No. 50-456


Dear Mr. Martin:

Attached is the report of the Steam Generator Eddy Current Examination performed at Braidwood Station. In accordance with Braidwood Technical Specification 4.4.5.5.b and 6.9.2, the complete steam generator tube inservice inspection results shall be submitted to the Commission within 12 months following completion of the inspection. The Steam Generator Eddy Current Surveillance was completed October 14, 1992.

Fifty percent of the tubing received a full length bobbin coil inspection with the remainder of the tubes being inspected through the U-Bend from the hot leg side. A rotating pancake coil was used to confirm and characterize all distorted indications found through the bobbin examinations.

Attached is a report summarizing the inspection results. Included in the report are indication lists and maps, a guide to abbreviations used in the indication list, and a list of certified personnel performing the eddy current examinations.

If there are any questions regarding this information, please contact Mr. Mike Sears, (815) 458-2801, ext. 2251.


K. L. Kofron
Station Manager
Braidwood Station

KLK/MS/dla
Attachment

cc: R. Assa, NRR
B. Clayton, RIII
Sr. Resident Inspector, Bwd.
M. Sears
NRC Document Control Desk

010058

9310040146 930927
PDR ADDCK 05000456
Q PDR

AC47