

PALISADES PLANT  
Docket 50-255  
License DPR-20

NRC FORM 366  
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I P A L 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 56 57

CON'T  
01 REPORT SOURCE 60 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80 81  
7 8

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a containment entry through the personnel air lock, it was noted that  
03 the air lock inner door was not fully closed, as evidenced by the sound of  
04 air rushing past the inner door seals. Accordingly, containment integrity  
05 requirements were not met during the period of time that the outer door was  
06 open to gain access to the lock, and had apparently not been met during the  
07 previous exit from the airlock on June 22, 1982. Condition reportable per  
08 T.S. 6.9.2.A(3) and 3.6.1.  
7 8 9

09 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP. SUBCODE 15 VALVE SUBCODE 16  
7 8

17 LER-RO REPORT NUMBER 18 19 EVENT YEAR 20 21 22 23 24 25 26 27 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32  
ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 38 ATTACHMENT SUBMITTED 39 40 NPD-4 FORM SUB 41 PRIME COMP. SUPPLIER 42 43 COMPONENT MANUFACTURER 44 45 46 47

10 Containment integrity was lost because personnel did not properly shut the  
11 inner door on 6-22-82 and an interlock was out of adjustment, allowing the  
12 outer door to open before complete closure of inner door. To prevent recur-  
13 rence, operating instructions have been posted, the interlock was adjusted  
14 and an alarm will be installed to warn that the inner door is open.  
7 8 9

15 FACILITY STATUS 16 17 POWER 18 19 OTHER STATUS 20 21 METHOD OF DISCOVERY 22 23 DISCOVERY DESCRIPTION 24 25  
7 8 9

16 Z 26 27 Z 28 29 NA 30 31 NA 32 33 NA 34 35 NA 36 37 NA 38 39 NA 40 41 NA 42 43 NA 44 45 NA 46 47 NA  
7 8 9

17 0 0 0 0 37 E 38 NA 39 NA 40 NA 41 NA 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA  
7 8 9

18 0 0 0 0 40 NA 41 NA 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA  
7 8 9

19 Z 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA  
7 8 9

20 N 44 NA 45 NA 46 NA 47 NA  
7 8 9

NRC USE ONLY  
68 69 70 71 72 73 74 75 76 77 78 79 80

8207270012 820708  
PDR ADOCK 05000255  
S PDR

J G Keppler, Administrator  
Attachment to LER 82-19  
Consumers Power Company  
Palisades Plant  
July 8, 1982

2

During a containment entry on June 24, 1982, it was noted that the personnel air lock inner door status light indicated the inner door was not shut. The personnel making the entry verified by direct visual observation (through the viewing window) that the inner door was shut and then opened the outer door. After entering the lock and closing the outer door, the personnel heard air rushing through the inner door. When the inner door handwheel was turned approximately 1/8 turn, air leakage stopped and the open indication light was extinguished.

Based on the as-found condition of the inner door, it is concluded that containment integrity was also broken during the previous containment exit on June 22, 1982, when the inner door was apparently improperly closed and the outer door was opened.

The cause of the event was personnel error in that the inner door was not properly closed on June 22 and that the personnel making the entry did not notify the Shift Supervisor of the open indication prior to making the entry on June 24. However, several mechanical problems contributed to the personnel error:

- 1) The inner door handwheel had a "hard spot" just before it is fully closed, giving the feeling of being closed.
- 2) The interlock which prevents both doors from being open at the same time was out of adjustment, allowing the outer door to open when the inner door was not fully closed.
- 3) There is no indication (ie, light or audible alarm) inside the personnel lock of inner door position.

To prevent recurrence, the interlock will be adjusted and an attempt will be made to reduce the "hard spot" on the inner door handwheel. Additionally, an alarm and indicating light system will be installed to warn the operator inside the personnel lock that the inner door is not fully closed.

Until the permanent corrective action can be completed, several interim measures have been taken:

- 1) An Operations Department memorandum has been issued to all Shift Supervisors instructing them on the proper procedures for personnel lock operation, including the existence of the "hard spot" and the interlock misadjustment.
- 2) Control Room status boards have been updated to indicate personnel lock problems.
- 3) Caution tags have been hung on the personnel lock doors warning of the problems.
- 4) Operating instructions have been posted for the personnel lock doors and the door indicating lights have been labeled to avoid confusion.