

CONTROL BLOCK:

| | | | | | | |
|---|--|--|--|--|--|-----|
| 1 | | | | | | (1) |
|---|--|--|--|--|--|-----|

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---------------|----|----|----------------|----|-----|--------------|----|----|-----|----|---|---|---|---|---|---|---|-----|---|---|---|---|---|-----|--|--|-----|
| 0 | 1 | N | C | B | E | P | 1 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | | (5) |
| 7 | 8 | 9 | LICENSEE CODE | 14 | 15 | LICENSE NUMBER | 25 | 26 | LICENSE TYPE | 30 | 57 | CAT | 58 | | | | | | | | | | | | | | | | | |

CON'T

| | |
|---|---|
| 0 | 1 |
| 7 | 8 |

REPORT SOURCE

| | | | | | | | | | | | | | | | | | | | | | | | | |
|----|----|---------------|---|---|---|---|----|----|------------|---|---|---|---|----|----|-------------|---|---|---|---|----|---|---|---|
| L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 5 | 7 | 0 | 6 | 1 | 9 | 8 | 2 | 8 | 0 | 7 | 1 | 6 | 8 | 2 | 9 |
| 60 | 61 | DOCKET NUMBER | | | | | 68 | 69 | EVENT DATE | | | | | 74 | 75 | REPORT DATE | | | | | 80 | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During plant operation, routine surveillance revealed post-accident monitoring Control

0 3 | Room recorder/indicator, 1-CAC-AR-1263, was indicating an unexpected downward trend in

0 4 | drywell oxygen concentration. At the time redundant instrument, 1-CAC-AR-1259, was

0 5 | indicating an expected trend in drywell oxygen concentration. This event did not

0 6 | affect the health and safety of the public.

0 7

0 8

Technical Specifications 3.3.5.3, 3.6.6.4, 6.9.1.9b

80

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------|---|-------------|----|----|----|-----------------------|------------|----|----|----|---------------|-----------------|----|----|----------------|----|-------------|----|----|----|--------------|----|----|----|--------------|---------------|---------------|----|-----------------|---------------|-----------------|----|-------|----|----------------------|----|------------------|----|----------------------|----|------------------------|----|----|
| 09 | | SYSTEM CODE | | S | E | 11 | CAUSE CODE | | E | 12 | CAUSE SUBCODE | | E | 13 | COMPONENT CODE | | | | I | N | S | T | R | U | 14 | COMP. SUBCODE | | Y | 15 | VALVE SUBCODE | | Z | 16 | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | | | |
| LER/RO REPORT NUMBER | | EVENT YEAR | | 8 | 2 | SEQUENTIAL REPORT NO. | | 0 | | 6 | 6 | OCCURRENCE CODE | | 0 | | 3 | REPORT TYPE | | L | | REVISION NO. | | 0 | | ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | | |
| 17 | | 21 | | 22 | 23 | 24 | | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 |
| E | | F | | 19 | Z | | 20 | | Z | | 21 | | 0 | | 0 | 0 | 0 | N | | 23 | | Y | | 24 | | N | | 25 | | B | | 1 | 3 | 5 | | | | | | | | | |

| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) | |
|---|---|
| 1 0 | The event was caused by an instrument output shift in the electromagnetic unit of the |
| 1 1 | monitor oxygen analyzer, 1-CAC-AT-1263-2. The electromagnetic unit was calibrated and |
| 1 2 | the analyzer, Model No. F3M3 was returned to service indicating expected drywell oxygen |
| 1 3 | concentrations. These analyzers will be replaced as part of an approved plant |
| 1 4 | modification. |

[illegible]

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521