

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 1 7 0 6 1 6 8 2 8 0 7 0 9 8 2 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in Mode 3, oil leakage from bearings of AFW Pump 2P-504 was observed.

0 3 The pump was taken out of service for repairs of the leak. There was no

0 4 consequence to the public health and safety due to the availability of the

0 5 other two 100% flow trains, and in addition there is no decay heat in the core.

0 6

0 7

0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
H H 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16

17 LER/RO REPORT NUMBER EVENT YEAR 8 2 21 22 SHUTDOWN METHOD Z 21 23 24 25 26 27 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32

ACTION TAKEN B 18 33 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 35 HOURS 0 0 0 0 37 38 ATTACHMENT SUBMITTED N 23 41 NPRD-4 FORM SUB. N 24 42 PRIME COMP. SUPPLIER A 25 43 COMPONENT MANUFACTURER Z 9 9 9 9 26 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The bearings on AFW Pump 2P-504 were leaking, continued operation without

1 1 repairs could have resulted in bearing failure. The leak was repaired and

1 2 the system was restored to operable status. No other corrective action was

1 3 needed.

1 4

1 5 FACILITY STATUS B 28 29 % POWER 0 0 0 29 30 OTHER STATUS NA 31 METHOD OF DISCOVERY B 31 32 DISCOVERY DESCRIPTION Operator observation 32

1 6 ACTIVITY CONTENT Z 33 34 RELEASED OF RELEASE Z 34 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 38 39 DESCRIPTION NA 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION NA 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION NA 43

2 0 PUBLICITY ISSUED N 44 45 DESCRIPTION 45

NRC USE ONLY