

HOPE CREEK GENERATING STATION

BAILEY 862 SYSTEM LOGIC MODULE

FAILURE DATA REPORT

PERIOD: THIRD QUARTER 1990

PREPARED BY:

J. A. Rosan
SYSTEM ENGINEER

10/01/90
DATE

APPROVED BY:

R. H. Shapiro
TECHNICAL ENGINEER

10/11/90
DATE

BAILEY SSLM REPORT

A. SUMMARY OF FAILURES BY MONTH DURING REPORT PERIOD

JULY 1990

- 1) 07/02/90 1DC652 SLOT 5-4-12 O-1227 N-2595
INPUT BUFFER #2 FAILED. CONFIRMED FAILURE
W.O. 900702079
PROBLEM: DUAL VALVE POSITION INDICATION AT MCR FOR
1EAHV-2197D, BACKWASH WTR FROM STRAINER DF509.
- 2) 07/10/90 1CC652 SLOT 1-3-2 O-2202 N-0652
INPUT/OUTPUT BUFFER #7 FAILED. CONFIRMED FAILURE
PROBLEM: CONTROL/DIESEL 1E SWGR BRKR 10-A-403-01 DID
NOT REMAIN CLOSED UPON DEMAND FROM MCR.
- 3) 07/17/90 1CC652 SLOT 4-10-10 O-0870 N-0556
T/S-CARD REPLACEMENT ONLY. NOT A FAILURE
W.O. 900718144
PROBLEM: DUAL 1AP400 (HVAC) PUMP RUN INDICATION, CARD
REMOVED AND TESTED ON SSLM TESTER. NO PROBLEM FOUND ON
LOGIC MODULE. DECISION MADE TO REPLACE CARD.
- 4) 07/30/90 1BC652 SLOT 8-9-5 O-1228 N-0110
OUTPUT BUFFER #3 INTERMITTENT CONFIRMED FAILURE
W.O. 900730093
PROBLEM: 1FCHV-F059 (RCIC STM EXH VLV) LOSS OF MCR
POSITION INDICATION.

TOTAL MONTHLY FAILURES = 3 SSLM'S

AUGUST 1990

- 1) 08/11/90 1DC653 SLOT 9-9-9 O-1549 N-2242
INPUT/OUTPUT BUFFER #1 FAILED. CONFIRMED FAILURE
W.O. 900811112
PROBLEM: 1BBHV-F031B (RX RECIRC PMP "B" DISCH), LOSS
OF VALVE POSITION INDICATION.
- 2) 08/14/90 1CC652 SLOT 5-10-12 O-0872 N-0183
T/S-CARD REPLACEMENT ONLY. CONFIRMED FAILURE
W.O. 900813167
PROBLEM: 1ABHV-3631B (CNTMNT ISOL VALVE OVRD/PF LOGIC)
CAUSING ANN D1-B3 TO ALARM. FOUND FLPA CHIP LOOSE IN
SOCKET. SLIGHTEST VIBRATION CAUSED INTERMITTENT
FAILURES. REWORKED FLPA AND CARD RETESTED SAT.

- 3) 08/20/90 1BC653 SLOT 8-3-8, O-0241 N-0342
T/S-CARD REPLACEMENT ONLY. NOT A FAILURE
W.O. 900820122
PROBLEM: 1B-P-209 (RACS "B" PMP) WOULD NOT STOP FROM
MCR. T/S FOUND LOOSE CONNECTOR ON 7-1-3. DURING T/S
CAUSED LOGIC INPUT FAILURE ON LOGIC CARD. REQUIRED
REPLACEMENT. T/S FAILURE AND NOT A SERVICE FAILURE.

TOTAL MONTHLY FAILURES = 2 SSLM

SEPTEMBER 1990

TOTAL MONTHLY FAILURES = 0 SSLM

TOTAL QUARTERLY FAILURES = 5 SSLM'S

B. FAILURE RATE DATA

- 1) 24 CONFIRMED FAILURES FROM 10/01/89 THRU 09/30/90.
- 2) 2278 SSLM POPULATION
- 3) ANNUAL FAILURE RATE PERCENTAGE:
 - a. $24 \div 2278 = 0.01009 \times 100 = 1.01 \%$
- 4) MEAN TIME BETWEEN FAILURES DETERMINATION:

MTBF FROM 10/01/89 THRU 09/30/90.

 - a. 12 MONTH SERVICE HOURS = 8760 HOURS
 - b. TOTAL MODULE SERVICE HOURS
$$8760 \times 2278 = 19.95 \times 10^6$$
$$19.95 \times 10^6 \div 24 \text{ FAILURES} = 831,250 \text{ HOURS}$$
 - c. $24 \div 19.95 \times 10^6 = 1.20 \text{ FAILURES PER MILLION HOURS FAILURE RATE.}$

C. COMPARISON STANDARD

- 1) THE IEEE 500 STANDARD EXPECTED FAILURE RATE OF SOLID STATE COMPUTATION DEVICES IS EQUAL TO 1.19 FAILURES PER MILLION HOURS FAILURE RATE.
- 2) THE HCGS BAILEY 862 SSLM FAILURE RATE FROM OCT 1989 THRU SEPT 1990 IS EQUAL TO 1.20 FAILURES PER MILLION HOURS FAILURE RATE.

D. ANALYSIS

- 1) HCGS BAILEY 862 SSLM FAILURE RATE APPEARS TO HAVE STABILIZED IAW IEEE 500 STANDARD.
- 2) THE CONFIRMED FAILURE DATED 07/10/90 DID AFFECT A SAFETY RELATED FUNCTION (LOSS OF "C" VITAL BUS). THE PROBLEM WAS ENCOUNTERED DURING A RELAY DEPARTMENT 31 DAY DEGRADED VOLTAGE SURVEILLANCE TEST ON THE 10A403 BUS. THE SSLM FAILURE CAUSED THE LOSS OF POWER ON THE 10A403 BUS DURING A TRANSFER OF BREAKERS 52-40301 AND 52-40308. VARIOUS FUNCTIONS THEN TOOK PLACE, CAUSING A POWER REDUCTION TO 95% RX PWR. UPON STABILIZATION, SYSTEMS WERE RESET AND PWR RESTORED TO 100%.
ALL OTHER FAILURES AFFECTED INDICATION ONLY.

E. RECOMMENDATIONS

- 1) NONE