

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

REPORT SOURCE L 0 5 0 0 0 3 3 5 0 7 0 2 8 2 0 8 0 2 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal operation it was found that containment isolation valve V5201 would not shut. The penetration was isolated by shutting V5204 and pulling the fuses to deenergize it in accordance with T.S.3.6.3.1.b. The valve was repaired and placed back in service. This is the fourth similiar occurrence. (SEE LER's 76-24,77-28 and 80-06 Valves Inoperable) This is on a 3/8in. sample line and the redundant isolation valve, V5204, was working. Public Health and safety was maintained.

SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V E X 14 COMP SUBCODE F 15 VALVE SUBCODE D 16

LER/RO REPORT NUMBER 17 8 2 21 22 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER H 2 3 0 26

ACTION TAKEN A 13 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

V5201 is a containment Isolation valve for the pressurizer surge line sample piping. The packing was leaking and caused the valve to become inoperable. The line was isolated with a manual isolation valve in containment and valve V5201 was repaired and tested. The valve was placed back inservice and no further problems were noted.

FACILITY STATUS E 28 1/2 POWER 0 9 9 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION N/A 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY N 44 NRC USE ONLY 45

NAME OF PREPARER P.L. Pace PHONE (305) 552-3654