

LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE			
01	M	N	M	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	1	
7	8	9				14	15										25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CONT	P	O	T	L	0	5	0	-	0	2	6	3	0	9	1	2	7	5	1	1	1	1	7	5
7	8	57	58	59	60	61						66	68	69	74	75									

EVENT DESCRIPTION

02	While Conducting local leak test it was found that main steam isolation valves	80
03	AO-2-80C and 86C were leaking in excess of Technical Specification acceptance cri-	80
04	teria. Pilot and main poppet seats were lapped. Retested and passed local leak	80
05	test for combined leakage. Similar previous events. (AO-267/75-17-2)	80
06		80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER					VIOLATION			
07	C	D	F	V	A	L	V	E	X	A	A	5	8	5	Y	
7	8	9	10	11	12				17	43	44				47	48

CAUSE DESCRIPTION

08	Atwood and Morrill Company, 18-inch Y Type Globe Valve, Drawing 20786-H. Cause of	80
09	leakage unknown. Pilot and poppet seats lapped.	80
10		80

FACILITY STATUS	% POWER	OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	
11	H	0	0	B	NA	
7	8	10	12	44	45	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	NA	NA
7	8	10	45

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13	0	NA
7	8	13

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14	NA
7	12

OFFSITE CONSEQUENCES

15	NA	80
--	----	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16	NA
7	10

PUBLICITY

17	NA	80
--	----	----

ADDITIONAL FACTORS

18	NA	80
--	----	----

19	<div style="display: flex; justify-content: space-between;"> 9105070377 751111 CF ADDCK 05000263 </div>	80
--	---	----

NAME T. W. Grue PHONE 612/295-5151