

SENSEE EVENT REPORT

CONTROL BLOCK:

1					6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE				
0	1	M	N	M	N	P	I	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9					14	15									25	26					30	31	32

01 CONT		CATEGORY P 0		REPORT TYPE 1	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 6 3			EVENT DATE 0 1 1 6 7 5			REPORT DATE 0 2 0 7 7 5		
7	8	57	58	59	60	61			68	69			74	75

[illegible]

02 While performing a local leak rate test, the HPCI Turbine Exhaust Check Valve, 80
7 8 9
03 HPCI-9, was found leaking in excess of the acceptance criteria. This line does 80
7 8 9
04 not have a redundant isolation valve. Similar events occurred in July, 1972 and 80
7 8 9
05 during spring refueling outages 1973 and 1974. Straighten bent hinge (AO 263/75-1) 80
7 8 9
06 80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
07	S D	E	V	A	L	V	E	N	A	A	3	9	5	Y
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21

CAUSE DESCRIPTION

08	Bent hinge pin prevented proper seating. 16-inch - 150	80
09	psi swing check valve, Anchor Valve Company, Dwg. No. 2374-5. Straighten bent	80
10	hinge pin, lapped disc and tested satisfactory.	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	H	0	0	0	NA	B	NA			
7	8	10	11	12	13	44	45	46	80	

FORM OF ACTIVITY RELEASED: 1 2
CONTENT OF RELEASE: 3 4
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	NA

OFFSITE CONSEQUENCES

15	NA	
----	----	--

LOSS OR DAMAGE TO FACILITY

PUBLICITY

17	NA	9105130409	750210	
----	----	------------	--------	--

ADDITIONAL FACTORS

18	NA
----	----

NAME L. L. Nolan

PHONE 612/295-5151