

## LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 1 | 1 | 2 | 5 | 8 | 2 | 8 | 1 | 2 | 2 | 2 | 8 | 2 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On November 25, 1982, fire detection zone 2-8 (Steam Tunnel Roof, 166 feet Auxiliary  
0 3 | Building) and zone 2-7 (Set Down Area, 166 feet Auxiliary Building) alarmed with no  
0 4 | fire or smoke present and would not reset. Hourly fire watches were established in  
0 5 | accordance with T.S.3.3.7.9.a. The event had no effect on the health and safety of  
0 6 | the public and did not constitute a threat to plant safety. The event is being  
0 7 | reported pursuant to T.S.6.9.1.13.b.

0 8 | \_\_\_\_\_  
7 8 9 80

0 9 | A | B | 11 | X | 12 | Z | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
17 | 8 | 2 | 1 | 4 | 4 | 0 | 3 | L | 0  
21 22 23 24 25 26 27 28 29 30 31 32  
LER/RO REPORT NUMBER SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | A | 25 | H | 2 | 6 | 0 | 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Maintenance personnel investigating found smoke detector N531G (zone 2-8) and N707B  
1 1 | (zone 2-7) in alarm. The cause of the alarms is unknown. The detectors were reset  
1 2 | and a functional test (06-IC-SP65-0-1001) was performed and completed satisfactorily.  
1 3 | The detectors were restored to operable status on November 26, 1982. This is a final  
1 4 | report.

1 5 | B | 26 | 0 | 0 | 0 | 29 | NA | A | 31 | Alarmed Condition  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
1 6 | Z | 33 | Z | 34 | NA | NA | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
1 8 | 0 | 0 | 0 | 40 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PERSONNEL INJURIES NUMBER DESCRIPTION  
1 9 | Z | 42 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
2 0 | N | 44 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PUBLICATION ISSUED DESCRIPTION  
NRC USE ONLY

NAME OF PREPARER Original signed by Ron Byrd

PHONE