

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4				5
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CA	58

CON'T

0 1 7 8
REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 1 0 1 9 8 2 8 1 2 2 3 8 2 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During plant operation performance of the Suppression Pool Level Indicators

0 3 Operability Test, PT-08.1.6, revealed the following: 1-CAC-LR-2602 indicated

0 4 -28.5", 1-CAC-LI-2601-1 indicated -30.0", 1-CAC-LI-2601-3 indicated -29.5", and

0 5 1-CAC-LI-3342 indicated -28.0" while the local level indicator showed -25.5". This

0 6 value exceeds specifications and is being reported in LER 1-82-135. This event did

0 7 not affect the health and safety of the public.

Technical Specifications 3.3.5.3, 6.9.1.9b

SYSTEM CODE I E 11		CAUSE CODE B 12		CAUSE SUBCODE A 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE T 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 1 1 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 1		LER/RO REPORT NUMBER 17	
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER B 0 4 C 26		ACTION TAKEN X 33		FUTURE ACTION Z 34		EFFECT ON PLANT Z 35	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The investigation determined a change in the trickle flow to the wet reference leg

1 1 of the LI-2601 and 3 indicators common transmitter; 1-CAC-LT-2601 had caused an

1 2 incorrect input signal to be sent to the indicators. Trickle flow to the transmitter,

1 2 Model No. BQ15221, was adjusted and the subject indicators were returned to service.

1 4 7 8 9 80

1		5		FACILITY STATUS		E		(28)		% POWER		0		5		9		(29)		OTHER STATUS		(30)		METHOD OF DISCOVERY		B		(31)		DISCOVERY DESCRIPTION		(32)	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) 10 (34) NA NA

7 8 9 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES			TYPE		DESCRIPTION	
NUMBER			TYPE		DESCRIPTION	
1	7	000	(37)	Z	(38)	NA

PERSONNEL INJURIES		DESCRIPTION		MA	
NUMBER					
1	8	0	0	0	40

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	

7 8 9 10 80
PUBLICATION
ISSUED DESCRIPTION (45)
8212300317 821223
PDR ADPOCK 05000325
PDR
NRC USE ONLY

2 0 N (44) S NA 68 69 80

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

NRC USE ONLY

GPJ 917-926

Facility: BSEP Unit No. 1

Event Date: October 19, 1982

As a result of previously reported events involving this instrumentation on both units, plant modification packages have been developed. These modifications will install a condensing pot in the reference leg of each subject instrument transmitter in order to increase the accuracy and reliability of these instruments. In addition, these modifications will remove the present requirement to have flow in each subject reference leg to ensure it is full.