

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | T | N | S | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | C

CONT

0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 7 | 7 | 1 | 1 | 2 | 5 | 8 | 2 | 8 | 1 | 2 | 2 | 2 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | Unit 1 in mode 5 with RCS temperature at 117 degrees F and atmospheric pressure. On
0 3 | 11/25/82, the containment lower airlock door failed the local leak rate test, (surveill-
0 4 | ance instruction SI-159.1). Unit 1 in mode 5 with RCS temperature at 115 degrees F
0 5 | and atmospheric pressure. On 11/28/82, the containment upper airlock door failed the
0 6 | local leak rate test. This condition was discovered in mode 5 but was assumed to have
0 7 | existed in applicable modes per LCO 3.6.1.3. There was no effect upon public health
0 8 | and safety. Previous occurrences - three (SQRO-50-327/81108, 81027, and 82064).

0 9 | SYSTEM CODE | S | A | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | P | E | N | E | T | R | 14 | COMP. SUBCODE | A | 15 | VALVE SUBCODE | Z | 16

17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | EVENT YEAR | 8 | 2 | 22 | SEQUENTIAL REPORT NO. | 1 | 3 | 9 | 24 | OCCURRENCE CODE | 0 | 3 | 28 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32

18 | ACTION TAKEN | B | 19 | FUTURE ACTION | X | 20 | EFFECT ON PLANT | Z | 21 | SHUTDOWN METHOD | Z | 22 | HOURS | 0 | 0 | 0 | 0 | 27 | ATTACHMENT SUBMITTED | N | 23 | NPD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | C | 3 | 1 | 0 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The lower airlock and upper airlock doors (X-2A and X-2B) were leaking through the
1 1 | loose or damaged packing in the handwheel packing box. The packing was replaced in
1 2 | each case and the doors were retested satisfactorily. The packing problem is being
1 3 | investigated and a preventive maintenance program will be developed and implemented
1 4 | until further action is necessary.

1 5 | FACILITY STATUS | G | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance testing | 32

1 6 | ACTIVITY RELEASED OF RELEASE | Z | 33 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

NRC USE ONLY

Name of Preparer: A. M. Carver /M. R. Harding

Phone: (615) 751-0349