


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38 39

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 55

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 2 9 6 7 1 1 2 4 8 2 8 1 2 2 2 0 2 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

TIME	CAUSE	CAUSE	COMP.	VALVE
0 2	During normal operation on unit 3, while performing SI 4.2.B-69 (Reactor High-Pressure			
0 3	pressure switch, PS-3-204D, had an as-found setpoint of 1125.9 psig. T.S. Table			
0 4	3.2.B trip level setting is - 1120 psig. There was no effect on the health or			
0 5	safety of the public. A redundant switch was available and operable.			
0 6				
0 7				
0 8				

7 8 9

7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE				
0	9		I	B	E	E	I	N	S	T	R	U	S	Z		
7	8		9	10	11	12	13	14	15	16	17	18	19	20		
(17) LER/RO REPORT NUMBER			EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
8			2			0		5		0		3		0		
21			22		23	24		25		26		27		28		
ACTION TAKEN		FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
F		X	Z	Z	0				Y		N		N		S	
33		34	35	36	37				40		41		42		43	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1	0	Pressure switch, PS-3-204D, calibration had drifted. The static-O-ring model
1	1	9N-AA45-X9-TT pressure switch was recalibrated, functionally tested, and returned
1	2	to service. This is considered a random event and no further recurrence control
1	3	is required.
1	4	

7 8 9 FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 1 9 5 NA B Surveillance testing

7 8 9 ACTIVITY CONTENT (35) LOCATION OF RELEASE (36)

1 6 1 2 NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	

PERSONNEL INJURIES

NUMBER		DESCRIPTION
1	8	NA
2	9	
3	10	
4	11	
5	12	

8301030126 821222

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

PUBLICITY (45)
 ISSUED (44) NA
 NRC USE ONLY

NAME OF PREPARER Bobby J. Irby

PHONE: (205) 729-0841

LER SUPPLEMENTAL INFORMATION

BFRO-50-296 / 82055 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b.(1) * Date Due NRC 12/24/82

Event Narrative:

Units 1 and 3 were operating normally at 100-percent power and 95-percent power, respectively. Unit 2 was in a refueling outage. Only unit 3 was affected by this event. During the performance of Surveillance Instruction (SI) 4.2.B-69 (Reactor High Pressure), pressure switch, PS-3-240D, had an as-found setpoint of 1125.9 psig. Technical Specification (TS) Table 3.2.B required trip setting is equal to or less than 1120 psig. Pressure above the setpoint trips recirculation pump "B".

Pressure switch PS-3-204D calibration had drifted. The static-O-ring model 9N-AA45-X9-TT pressure switch was recalibrated, functionally tested, and returned to service. There was no effect on the health or safety of the public. A redundant switch was available and operable. This is considered a random event and no further recurrence control is required.

* Previous Similar Events:

BFRO-50-259/81048
260/78023, 80030

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP