

No. 3-82-25/3L

This LER deals with the torus narrow range level transmitter.
(Per Tech. Spec. Table 3.2.F.)

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 3 2 0 0 - 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 26 27 LICENSE TYPE 30 31 CAT 58

CON'T
 01 REPORT SOURCE L 6 0 5 0 - 0 2 7 8 7 1 2 1 4 8 2 8 0 1 1 1 8 3 9
 7 8 9 DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
 02 During normal operation, operator observed torus normal range level
 03 recorder not responding to changes in level. Level transmitter LT9027A
 04 was taken out of service to investigate the problem. After verification
 05 that transmitter and sensing lines were not plugged, transmitter was
 06 calibrated and returned to service on 12/17/82. On 12/18/82, a similar
 07 event took place and the transmitter was again taken out of service.
 08 The redundant level indication remained in service during both events.
 7 8 9

09
 7 8 9 SYSTEM CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15
 IF 11 E 12 E 13 IN STRU 14 T 15 Z 16

17 LER/RO REPORT NUMBER 18 EVENT YEAR 19 SEQUENTIAL REPORT NO. 20 OCCURRENCE CODE 21 REPORT TYPE 22 REVISION NO.
 8 2 2 0 2 5 0 3 L 0
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

ACTION TAKEN 33 EFFECT ON PLANT 34 SHUTDOWN METHOD 35 HOURS 36 ATTACHMENT SUBMITTED 37 NPD-4 FORM SUB. 38 PRIME COMP. SUPPLIER 39 COMPONENT MANUFACTURER
 E 18 E 19 Z 20 0 0 0 0 N 23 N 24 N 25 F 1 8 0 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
 10 Following the second event the displacer to force arm connection in the
 11 level transmitter was found to not be centered. The force arm was
 12 centered and the transmitter was returned to service on 12/22/82. The
 13 centering problem, which caused intermittent operation is believed to
 14 also have been cause of first event.
 7 8 9

15 FACILITY STATUS 16 % POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION 20
 E 28 0 9 3 29 NA A 31 Operator observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

21 ACTIVITY CONTENT 22 RELEASED OF RELEASE 23 AMOUNT OF ACTIVITY 24 LOCATION OF RELEASE 25
 Z 33 Z 34 NA NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

26 PERSONNEL EXPOSURES NUMBER 27 TYPE 28 DESCRIPTION 29
 0 0 0 37 Z 38 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

30 PERSONNEL INJURIES NUMBER 31 DESCRIPTION 32
 0 0 0 40 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

33 LOSS OF OR DAMAGE TO FACILITY TYPE 34 DESCRIPTION 35
 Z 42 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

36 PUBLICITY ISSUED 37 DESCRIPTION 38
 N 44 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

39 NRC USE ONLY
 40 41 42 43 44 45 46 47 48 49 50

8301260394 830111
 PDR ADOCK 05000278
 R PDR
 M. J. Cooney
 PHONE 215 - 841-5020