

No. 2-82-42/3L

The following LER describes the finding of two snubbers on two separate systems being disconnected during a system shutdown. Technical Specification .11.D.4 is applicable.

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 2 7 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
 01 REPORT SOURCE 1 6 0 5 0 - 0 2 7 7 7 1 2 1 0 8 2 8 0 1 1 0 8 3 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 02 During unit shutdown while performing ST 9.15, the snubber surveillance
 03 test, it was discovered that a feedwater snubber (6-DDNL-5-6) inside
 04 the drywell was not attached to its anchor. Another individual reported
 05 a HPCI exhaust line snubber (23-HBS-36) had been disconnected and was
 06 not operable. Engineering has documented that a single snubber per
 07 system may be disconnected without affecting the safety of the system.
 08 Technical Specification 3.11.D.4 is applicable.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 02 Z Z 11 A 12 C 13 S U P P O R T 14 D 15 Z 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE DOE REPORT TYPE REVISION NO.
 17 8 22 1 0 4 2 1 0 3 1 0
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 17 A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 A 25 3 2 2 26
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 10 It was concluded that the feedwater snubber was improperly installed and
 11 became disconnected during operation. No specific cause for the HPCI
 12 snubber can be determined other than the possibility that a craftsman
 13 mistakenly disconnected it. Both snubbers were properly reinstalled and
 14 verified operable prior to startup. Foremen will be reinstructed.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 15 G 28 0 29 N/A 30 B 31 Personnel Observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONT. IT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 16 Z 33 2 34 N/A 35 N/A 36
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 17 0 0 0 37 Z 38 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL INJURIES NUMBER DESCRIPTION
 18 0 0 0 40 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 19 Z 42 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PUBLICITY ISSUED DESCRIPTION
 20 N 44 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY
 21 N 45 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8301260470 830110
 PDR ADOCK 05000277
 S PDR
 M. J. Cronsey
 PHONE: (215) 841-5920