

## U.S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

/0/1/ CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)  
/V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
/0/1/ LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT  
REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/9/ (7) /0/1/1/3/8/3/ (8) /0/1/3/1/8/3/ (9)  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On January 13, 1983, with the Unit in Mode 1, the Individual Rod Position Indica-  
/0/3/ / tion (IRPI) for Rod P-06 in Control Bank "A" deviated from the group demand posi-  
/0/4/ / tion twice by greater than 12 steps with no rod motion. Within 8 hours, the /  
/0/5/ / position of the non-indicating rod was verified and the IRPI channel was returned/  
/0/6/ / to service in compliance with the Action Statement. Thus the health and safety /  
/0/7/ / of the general public were not affected. These events are contrary to T.S. /  
/0/8/ / 3.1.3.2 and reportable pursuant to T.S. 6.9.1.9.b. /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE				
/0/9/	/I/F/ (11)	/E/ (12)	/E/ (13)	/I/N/S/T/R/U/ (14)	/Y/ (15)	/Z/ (16)			
	LER/RO	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.			
(17)	REPORT NUMBER	/8/3/	/-/	/0/1/3/	/ /	/0/3/	/L/	/-/	/0/
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	
/A/ (18)	/Z/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/Y/ (23)	/N/ (24)	/N/ (25)	/W/1/2/0/ (26)	

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / Erratic indication of the first event was caused by dirty contacts on the signal /  
/1/1/ / conditioning module. The contacts were cleaned and the channel was recalibrated /  
/1/2/ / and returned to service. One hour later, the channel indication again deviated /  
/1/3/ / from group demand position indication. The signal conditioning module was /  
/1/4/ / replaced, the channel was calibrated and returned to service. /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/	/E/ (28)	/1/0/0/ (29)	/ NA / (30)	/A/ (31) / Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/	/Z/ (33)	/Z/ (34)	/ NA /	/ NA /
PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION (39)	
/1/7/	/0/0/0/ (37)	/Z/ (38)	/ NA /	
PERSONNEL INJURIES	NUMBER	DESCRIPTION (41)		
/1/8/	/0/0/0/ (40)	/ NA /		
LOSS OF OR DAMAGE TO FACILITY (43)	TYPE	DESCRIPTION		
/1/9/	/Z/ (42)	/ NA /		
PUBLICITY	ISSUED	DESCRIPTION (45)		
/2/0/	/N/ (44)	/ NA /		
NAME OF PREPARER		W. R. CARTWRIGHT	PHONE	(703) 894-5151

NRC USE ONLY

/ / / / / / / / / / / / / / / /

Virginia Electric and Power Company  
North Anna Power Station, Unit No. 2  
Docket No. 50-339  
Report No. LER 83-013/03L-0

Attachment: Page 1 of 1

#### Description of Event

On January 13, 1983, with the Unit in Mode 1, the Individual Rod Position Indication (IRPI) for Rod P-06 in Control Bank "A" deviated from the group demand position twice by greater than 12 steps with no rod motion. At 1845, the IRPI for Rod P-06 indicated 198 steps with the group demand indicating 228 steps. At 2200, the IRPI was declared operable. At 2353, the channel again became erratic and was taken out of service. These events are contrary to T.S. 3.1.3.2 and reportable pursuant to T.S. 6.9.1.9.b.

#### Probable Consequences of Occurrence

At 0200 on January 14, 1983, the position of Rod P-06 was verified at 228 steps by the performance of a single thimble flux map. A unit rampdown to 30 percent had occurred but the position of Rod P-06 did not change since it is part of Control Bank "A". At 0959, IRPI for Rod P-06 was declared operable and returned to service. Since the channel was returned to service within 8 hours after determining the rod position by the movable incore detector system, the health and safety of the general public were not affected.

#### Cause of Event

A faulty signal conditioning module within the IRPI system caused erratic indication of the channel.

#### Immediate Corrective Action

For the first event the contacts of the signal conditioning module printed circuit card were cleaned, the channel was calibrated and returned to service. Approximately one hour later, the channel was again erratic and the card was replaced. The channel was again calibrated and returned to service.

#### Scheduled Corrective Action

No further action required.

#### Actions Taken to Prevent Recurrence

No further action required.

#### Generic Implications

There are no generic implications to these events.