

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CIA DIC P 1 2 0 0 - 1 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT
01 REPORT SOURCE L 6 0 5 1 0 1 0 0 2 1 7 5 7 0 1 1 0 7 1 8 3 8 0 2 0 3 1 8 1 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 Prior to fuel load, Steam Generator Blowdown Multipoint Flow Recorder 1-71
03 was discovered to be inoperable during a recorder check. The failure of this
04 recorder rendered the Steam Generator Blowdown Effluent Line Flow Rate
05 Measurement Device (FR-53) inoperable. FR-53 is required to be operable
06 by Technical Specification 3.3.3.9. All Technical Specification Action
07 Statements were satisfied, and no radioactive effluents were released.
08 This event has in no way affected public health and safety. (cont'd on att.)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
M C 11 E 12 B 13 I N S I T R I U 14 R 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 LER/RO REPORT NUMBER 18 EVENT YEAR 19 SHUTDOWN METHOD 20 SEQUENTIAL REPORT NO. 21 OCCURRENCE CODE 22 REPORT TYPE 23 REVISION NO.
8 3 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD FORM 108 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 Z 19 Z 20 0 0 0 0 22 Y 23 N 24 L 25 L 1 3 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 Failure of Multipoint Recorder 1-71 was caused by a broken print head drive
11 string, which was replaced and the unit returned to service.
12
13
14
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

15 FACILITY STATUS 16 % POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION 20
B 28 0 0 0 29 NA B 31 Routine Inspection
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT 17 RELEASED OF RELEASE 18 AMOUNT OF ACTIVITY 19 LOCATION OF RELEASE 20
Z 33 Z 34 NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES 18 NUMBER 19 TYPE 20 DESCRIPTION 21
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES 19 NUMBER 20 DESCRIPTION 21
0 0 0 40 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY 20 TYPE 21 DESCRIPTION 22
Z 47 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY 21 ISSUED 22 DESCRIPTION 23
IN 44 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER WILLIAM J. KELLY PHONE 805/595-7351

8302180175 830203
PDR ADOCK 05000275
S PDR

NRC USE ONLY

Attachment to LER 83-001/03L-0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (continued)

Reportable per Technical Specification Section 6.9.1.13.b.