

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	1	7	1	1	1	8	3	8	0	2	1	0	8	3	9
60	61									68	69					74	75						80
DOCKET NUMBER											EVENT DATE					REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On January 11, 1983, at 0200 while in Mode 1 at 50% power, Iodine Removal System (IRS) Valve 2HV-9398 was declared inoperable when it failed its Technical Specification surveillance test per Section 4.6.2.2.b. LCO 3.6.2.2 was invoked. The Action Statement associated with this LCO allows operations to continue for up to 72 hours before requiring the valve to be returned to service or initiate cooldown. The public health and safety were not affected as a result of this event.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2/

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1 0 A misaligned upper limit switch was the cause of this event. The limit switch

1 1 was readjusted and the valve returned to service at 1647 on January 11, 1983,

1 2 after a functional test in accordance with Procedure S023-3-3.30. No further action

1 3 is planned.

1	4	7	8	9											80																													
FACILITY STATUS					% POWER					OTHER STATUS (30)					METHOD OF DISCOVERY					DISCOVERY DESCRIPTION (32)					80																			
1	5	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	80
B (28)					0 5 0 (29)					N/A					B (31)					Surveillance Testing																								

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 33 7 34

AMOUNT OF ACTIVITY (35)
N/A

LOCATION OF RELEASE (36)
N/A

PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION	
1	7	0	0	0	(37) Z	(38)	N/A

8 9		11 12		13		8302250224 830210	
PERSONNEL INJURIES						PDR ADOCK 05000361	
NUMBER		DESCRIPTION		(41)		S PDR	
1	8	0	0	0	(40)		

8		9		11		12	
TYPE		DESCRIPTION					
1	9	Z	(42)	N/A			

7 8 9 10

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) N/A

NRC USE ONLY

NAME OF PREPARER

H.B. RAY

PHONE

714-492-7700