

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 3 6 1 7 0 1 1 4 8 3 8 0 1 1 1 8 3 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

With the plant in Mode 1, Train B post Loss of Coolant Accident (LOCA) hydrogen monitor

2AET-8111-2 failed to meet the Channel functional test as required by Technical

03
Specification Surveillance Requirement 4.6.4.1 and was declared inoperable

at 1600. There was no impact on plant operation or the health and safety.

of plant personnel or the public as a result of this occurrence since

the redundant Train A monitor remained operable throughout the event.

0 7

	7	8	9	SYSTEM	CANOE	CANOE		COMP	VALUE	80
	Q	8								

7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 S E E I N S T R U E Z

11 12 13 14 15 16

9 10 11 12 13 14 15 16 17 18 19 20

8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER RO REPORT NUMBER

EVENT YEAR

8 3

21 22

23

SEQUENTIAL REPORT NO.

0 0 8

24 25 26

27

OCCURRENCE CODE

0 3

28 29

REPORT TYPE

L

30

31

REVISION NO.

0

32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPIRM FORM 5-B PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

[A] (18) [X] (19) [Z] (20) [Z] (21) [0] [0] [0] [0] [N] (23) [N] (24) [A] (25) [G] [0] [8] [0] (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Inoperability of the monitor was due to a faulty detector associated with the
---	---	---

1 1 | monitor. The detector was replaced and the monitor was declared operable in

1 2 accordance with Procedure S023-II-1.10 on January 19, 1983, within the time

limits prescribed by the LCO 3.6.4.1 Action Statement. As corrective action,

the feasibility of design modifications to the monitors is being evaluated. If design modifications are shown to be necessary, they will be implemented

7 8 9 during the first refueling outage. 80

1	5	B	28	0	5	0	29	N/A		B	31	Surveillance Testing	
7	8	9		10	11	12	13	14	15	16	17	18	19
80													

ACTIVITY		CONTENT		AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
RELEASED		RELEASED			
1	6	Z	(33) Z (34)	N/A	N/A

[illegible]

NUMBER		TYPE		DESCRIPTION	
1	7	0	0	0	N/A
7	8	9	11	12	13

PERSONNEL INJURIES					
	NUMBER	DESCRIPTION	(41)		
1	0	0	0	0	N/A

7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION

1		9		Z		42		DESCRIPTION	
7	8	9	10	11	12	13	14	15	16
								N/A	
8302250226 830211									

ISSUED 20 N 44 (45) DESCRIPTION PDR ADQCK 05000361 PDR S NRC USE ONLY

7 8 9 10 68 69 80
HAY
Day
714-492-7700

NAME OF PREPARER

H.B. Ray

PHONE

714-492-7700

P.O. 917-926