

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0	8	W	B	E		E		I	N	S	T	R	S		Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
17		8	3	—		0	0	0	3	L		0			
23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM:UB.		PRIME COMP. SUPPLIER	
E	18	Z	19	Z	20	Z	21	0	0	N	23	N	24	L	25
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)															

1 0 Investigation revealed that pressure switch 1-PS-3-164 had failed with its contacts  
1 1 in the closed position which caused the valve not to open. The most probable cause  
1 2 for the failure of the Dual Snap Model 604 pressure switch is dirty contacts. The  
1 3 contacts were cleaned and calibration verified. The valve was returned to service  
1 4 on 01/19/83. No further action is planned at this time.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	C	28	0	0	3	29	NA	B	31	Operator observation			
7	8	9	10	11	12	13	14	44	45	46	80			
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	33	Z	34	NA			NA					
7	8	9	10	11	12	13	14	44	45	46	80			
PERSONNEL EXPOSURES			TYPE			DESCRIPTION								
1	7	0	0	0	37	Z	38	NA						
7	8	9	10	11	12	13	14	44	45	46	80			
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
1	8	0	0	0	40	NA								
7	8	9	10	11	12	13	14	44	45	46	80			
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	9	Z	42	NA										
7	8	9	10	11	12	13	14	44	45	46	80			
PUBLICITY			ISSUED			DESCRIPTION								
2	0	N	44	NA										
7	8	9	10	11	12	13	14	44	45	46	80			

8302280155 830217  
PDR ADOCK 05000327  
S PDR

NRC USE ONLY

Phone: (615) 751-0349