

Attachment to AEEM-83/0100

TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	4	1	6	7	0	1	1	3	8	3	8	0	2	1	8	8	3	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE							REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 13, 1983, fire rated door OC104 (Hot Machine Shop to Turbine Building)
0 3 | was blocked open to route a temporary discharge hose from the Hot Machine Shop sump
0 4 | to the Turbine Building floor drain system. An hourly fire watch was established in
0 5 | accordance with T.S.3.7.7. The event had no effect on the health and safety of the
0 6 | public and did not constitute a threat to plant safety. This is submitted as a
0 7 | Special Report pursuant to T.S.3.7.7 and is considered an interim report. A final
0 8 | report will be submitted by May 15, 1983.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The temporary discharge hose was routed through the doorway to discharge water
1 1 | from the Hot Machine Shop sump. The present system pump is inadequate (will not
1 2 | generate required head). A design change request has been initiated for pump
1 3 | modifications. In the interim, the door will be opened and fire watches will be
1 4 | established as required. Estimated restoration is mid-April.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	28	0	0	0	29	NA	A
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		Planned Action		LOCATION OF RELEASE	
1	6	Z	33	Z	34	NA	NA	NA	35
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40			NA	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42			NA			
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44			8302280301 830218 PDR AD0CK 05000416 S PDR		NRC USE ONLY	

NAME OF PREPARER

PHONE