

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 2000-000000-000341111145
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 REPORT SOURCE L0500003167011981330217839
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES
02 DURING START-UP OPERATIONS, MRV-220 (#2 S/G STOP VALVE) WAS FOUND WITH ONE OF TWO
03 PILLAR GUIDE BEARINGS DISPLACED. THE VALVE WAS IN THE CLOSED POSITION AND A
04 CLEARANCE WAS PLACED ON THE VALVE AT 1611 HOURS ON 1/19/83 TO ALLOW REPAIRS TO THE
05 GUIDE BEARING. THIS CONSTITUTED AN INOPERABLE VALVE; A LESS CONSERVATIVE CONDITION
06 THAN T.S. 3.7.1.5. THE OTHER S/G STOPS REMAINED OPERABLE, ACTION STATEMENTS WERE
07 MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES: 82-029.

03 SYSTEM CODE H B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE L 15 VALVE SUBCODE D 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
17 LER NO. REPORT NUMBER 83 0203 L 0
21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN F 18 FUTURE ACTION A 19 EFFECT ON PLANT C 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER H 2 5 8 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 THE REASON FOR THE FAILURE OF THE BEARING ASSEMBLY COULD NOT BE DETERMINED. SPLIT
11 RING RETAINERS WERE FABRICATED AND TACK WELDED INTO POSITION PER EMERGENCY
12 RFC-DC-1911. THE VALVE WAS TESTED SATISFACTORILY AND RETURNED TO SERVICE AT 2125
13 HOURS ON 1/19/83. SIMILAR VALVES WERE INSPECTED. NO ABNORMALITIES WERE NOTED. THE
14 BEARINGS WILL BE REPLACED DURING THE NEXT OUTAGE OF SUFFICIENT LENGTH.

15 FACILITY STATUS C 26 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
16 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
17 000 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
PERSONNEL INJURIES NUMBER DESCRIPTION
18 000 40 NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
19 Z 42 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
PUBLICITY ISSUED DESCRIPTION
20 N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

8302280362 830217
PDR ADOCK 05000316
S PDR

NRC USE ONLY

NAME OF PREPARER D. ROBINSON

PHONE: 616-465-5901