

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C T M N S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T
0 1 REPORT SOURCE L 6 0 5 0 10 0 3 3 6 7 0 1 2 1 8 3 8 0 2 1 8 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While at 100% steady state operation, the plant computer malfunctioned and was de-
0 3 clared inoperable. Operation continued per Technical Specification 3.2.1 and
0 4 3.1.3.3 for a 2 1/2 hour period. Power was reduced and core distribution was
0 5 monitored with excore detectors per Technical Specification 4.2.1.2. Similar events
0 6 82-051, 82-017, 81-009, 80-008, 79-020, 79-005, 78-027, 78-021, 78-012 and 77-041.
0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I F 11 E 12 A 13 R E L A Y X 14 C 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER/RO REPORT NUMBER 8 3
18 ACTION TAKEN A 18 Z 19
19 FUTURE ACTION
20 EFFECT ON PLANT B 20
21 SHUTDOWN METHOD Z 21
22 HOURS 0 0 0 7
23 ATTACHMENT SUBMITTED N 23
24 NPD-4 FORM 516 Y 24
25 PRIME COMP. SUPPLIER A 25
26 COMPONENT MANUFACTURER 1 1 0 1 1 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause was traced to a defective seek relay drive card, IBM Part No. 5800078.
1 1 The card was replaced and computer operation restored in 2 1/2 hours. No further
1 2 corrective action is required.
1 3
1 4

1 5 FACILITY STATUS E 28 1 0 0 29 NA 30 METHOD OF DISCOVERY A 31 Operator Observation 32
1 6 ACTIVITY CONTENT Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 37
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 NA 39 DESCRIPTION NA 40
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 NA 41 DESCRIPTION NA 42
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 NA 43 DESCRIPTION NA 44

2 0 PUBLICITY ISSUED N 44
8302280415 830218
PDR ADOCK 05000336 PDR
S