

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 7 8
9 14 15 25 26 30 37 38
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
0 1 7 8
REPORT SOURCE 60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Calibration of Unit 2 Hydrogen Recombiner temperature instrumentation (LIS-HG-01) was
03 performed in April of 1982 as required by Tech. Spec. 3.6.6.1 and 4.6.6.1.c.1. Calib
04 of this instrumentation was not performed until January 1983. After a technical eval
05 of the surveillance's "As Found" data, it was determined that the efficiency and oper
06 of the recombinder was not degraded or affected. This event is of minimal safety sign
07 cance since both recombiners (Unit 1 and Unit 2) were operable during this time perio
08

SYSTEM CODE M B 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE Z Z Z Z Z Z 14		COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 3 22		SEQUENTIAL REPORT NO. 0 0 4 26		OCCURRENCE CODE 0 3 29		REPORT TYPE L 31		REVISION NO. 0 32		COMPONENT MANUFACTURE Z 9 1 44	
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRE-A FORM SUB. N 24		PRIME COMP. SUPPLIER Z 25		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence was personnel error. A review of Technical Specifications

1 1 with the assistance of Operating to insure all requirements including Unit 2 instructions

1 2 tation required for Unit 1 operation are being met, is in progress and should be

1 3 completed by April 1, 1983.

1 4

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	B	0	0	0	NA			C	QA Audit				
ACTIVITY CONTENT RELEASED OF RELEASE						AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	Z	NA					NA					
PERSONNEL EXPOSURES NUMBER						TYPE			DESCRIPTION					
1	7	0	0	0	Z	NA								
PERSONNEL INJURIES NUMBER						DESCRIPTION								
1	8	0	0	0	NA									
LOSS OF OR DAMAGE TO FACILITY TYPE						DESCRIPTION								
1	9	Z	NA											
PUBLICITY ISSUED						DESCRIPTION			NRC USE ONLY					
2	0	N	8302280506 830217			PDR ADOCK 05000373			S PDR					

A. F. Trainor

PHONE: (815) 357-6761 *Ext 5

- I. LER NUMBER: 83-004/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373/374
- IV. EVENT DESCRIPTION:

Calibration of Unit 2 Hydrogen Recombiner temperature instrumentation (LIS-HG-01) was not performed in April of 1982. Recalibration of this instrumentation is required to be performed every eighteen months per Technical Specifications 3.6.6.1 and 4.6.6.1.c.1. Calibration of this instrumentation was not performed until January of 1983.

- V. PROBABLE CONSEQUENCES OF THIS OCCURRENCE:

This event was of minimal safety significance since both recombiners (Unit 1 and Unit 2) were operable during this time period. Unit 2's recombinder was declared operable after a technical evaluation of the surveillance's "As Found" data showed that the efficiency and operability of the recombinder was not degraded or affected. This is similar to DVR 1-1-82-245, LER 82-108/03L-0, Ler-82-002/03L-0.

- VI. CAUSE:

The cause of this occurrence was that the surveillance requirement for Unit 2 Hydrogen Recombiner was originally overlooked in the Technical Specifications.

- VII. CORRECTIVE ACTION:

An additional review of Technical Specifications with the assistance of Operating to insure all requirements, including Unit 2 instrumentation required for Unit 1 operation, are being met is in progress and should be completed by April 1, 1983.

Prepared by: A. F. Trainor